Solenoid / Torus – Fast Dump Investigations/Actions Taken

Date: February 18, 2019 Time: 08:00 – 10:30

<u>Attendees</u>: Pablo Campero, Brian Eng, Ruben Fair, Probir Ghoshal, Denny Insley, Carroll Jones, Dave Kashy, Tyler Lemon, Nicholas Sandoval, and Stepan Stepanyan

- 1. Results of Solenoid and Torus Fast Dump analysis presented by Ruben Fair
 - 1.1. On 2/17/2019 at ~ 04:12, both Solenoid and Torus fast dumped at full current 2416 A and 3770 A, respectively.
 - 1.2. Second Torus Fast Dump occurred on 2/17/2019 at ~ 17:50, due to low $\Delta P_{(sup-ret)}$; return pressure increased.
 - 1.3. Solenoid had a Controlled Fast dump on 2/17/2017 at ~ 17:55 due to PT8620 pressure signal that exceeded interlock threshold, as a consequence of Torus Fast Dump cryogenic conditions.
 - 1.4. Archived data pointed to spikes of LCW: 92_Flow_Makeup signal as the probable cause for the fast dumps of the Solenoid and Torus.
 - 1.5. From data archived for Solenoid MPS water supply and return pressure transducers, normal $\Delta P_{(sup-ret)} \sim 75$ psi.
 - 1.5.1. Right before Solenoid dumped, water return pressure increased from 43 psi to 63 psi, water supply pressure was stable ~112 psi; $\Delta P_{(sup-ret)} \sim 49$ psi
 - 1.5.2. The spikes for LCW: 92_Flow_Makeup signal represent the water tank being filled; units for LCW:92_Flow_Makeup are in [gal/min].
- 2. Solenoid and DBX PLCs issues.
 - 2.1. Solenoid PLC was running, but not communicating with Studio500 PLC software. Investigated issues and found it to be the same error as the Torus presented in October, 2018. (Error 701-800429B7: Failed to go online with the controller).
 - 2.2. Immediate actions taken to solve Solenoid PLC issues during the meeting:
 - 2.2.1. PLC power cycled, downloaded PLC code, and cleared errors and faults.
 - 2.2.2. Nick Sandoval, Dave Kashy verified PID values used for EV and heaters.
 - 2.3. Cryo DBX PLC lost communication during the meeting; it was power-cycled to recover communications and return the system back to normal operations.
 - 2.3.1. Brian Eng and Denny Insley verified set points for PID control of EV and heaters.
- 3. Planned activities to test Solenoid and Torus MPS water flows.
 - 3.1. Determine Torus and Solenoid MPS flows.
 - 3.2. Nick Sandoval will add PLC code logic to generate a Torus/ Solenoid Controlled Ramp Down if the $\Delta P_{(sup-ret)}$ goes below 55 psi (value TBD after test on 2/19/19).
 - 3.3. Carroll Jones will investigate solutions to stabilize the LCW pressure in the three Halls (A, B and C), to keep the $\Delta P_{(sup-ret)}$ stable for Solenoid and Torus MPS supply; possible solutions are:
 - 3.3.1. Add a relief valve to allow faster venting of nitrogen located in the tank.
 - 3.3.2. Change the level set points for batch fill switches.