

Hall D Slow Controls Meeting

Date: 11/14/19

Time: 10:00AM – 10:40AM

Attendees: Peter Bonneau, Aaron Brown, Hovanes Egiyan, Brian Eng, Tyler Lemon, Nick Sandoval, Tim Whitlatch, Beni Zihlmann

1. General:

- 1.1. Physics run has been delayed; will no longer begin on Nov. 25.

2. Solenoid Status

- 2.1. The power supply control board has been replaced with a “known good” board; so far, solenoid status is good.
- 2.2. The time change (Daylight Savings Time) has caused issues with the PXI. There is possibly a ROOT function to correct for this issue.

3. BCAL Chillers

- 3.1. The communications menu was factory reset for one of the chillers and was most likely the cause for the missing EPICS signals.
 - 3.1.1. There is a manual for fixing this if settings get changed again
- 3.2. The downstream chiller is pegged at 100%
 - 3.2.1. This is probably not an issue with the compressor cutoff switch; Nick is going to investigate
- 3.3. Nick and Tim are going to look into changing the PID Loop for the upstream chiller to fix issues.
- 3.4. Despite these issues, BCAL temperatures are stable.

4. ComCAL Installation/Survey

- 4.1. ComCAL chiller is off
- 4.2. Installation will possibly begin on Monday Nov. 18.
- 4.3. The LEDs have been fixed.
- 4.4. There are 9 bases that need to be swapped; should be ready by the time installation begins.

5. DIRC Interlocks

- 5.1. The DIRC Interlock screen needs to be changed.
 - 5.1.1. The Liquid Level interlock is now just an alarm. This needs to be reflected on the screen. Also, there is no longer a need for an “interlock override” button.
- 5.2. Tile temperatures have been added to the alarm system.
 - 5.2.1. A reset button may be needed to power cycle the FPGAs
- 5.3. After reset, the EPICS IOC needs to be rebooted once everything is powered on

6. Other Business

- 6.1. Tyler has fixed the bit order issue for the WEDM GUIs
- 6.2. The Target WEDM GUIs have been made and Chris Carlin has been contacted about placing them online.