



Detector Support Group

Weekly Report, 2016-05-25

Ongoing Projects

I. Hall B Magnet Slow Controls (Brian, Tyler, Peter, Amanda)

Task: Define/develop EPICS screen(s) for power supply status/control
 EDC: 03/15/2016
 Activity: None
 Comments: Leak checks and repairs are in progress.
 Vacuum has improved and turbo pumps can now be used.

Status: Delayed

II. Hall B Gas System: Slow Controls (Marc, Brian, George, Mary Ann.)

Task: Deploy LabVIEW based slow controls software system for **DC, LTCC, HTCC, SVT, MicroMegas, Forward Tagger, and RICH.**
 EDC: 07/31/2016.
 Activity: Developing software.
 Comments: Present status:

† Waiting on Hall B Engineering. †† Waiting for more information.

#	Location	Detector	Gas	Hardware		Software	Deployed	Tested
				Piping	Instrumentation			
1	Hall B	DC	Ar/CO ₂	X [†]	✓	✓	✓	X
2		HTCC	N ₂	X [†]	X	✓	✓	X
4		LTCC	C ₄ F ₁₀	X [†]	✓	✓	X	X
5		SVT	N ₂	X [†]	X	✓	✓	X
6		RICH	N ₂	X [†]	X	X	X	X
7		MicroMegas	Ar, C ₄ H ₁₀ , C ₂ H ₆ , Ne ^{††} , CF ₄	X ^{††}	X ^{††}	X ^{††}	X ^{††}	X ^{††}
8		Forward Tagger	N ₂	X	X	X	X	
9		EEL	SVT	N ₂	✓	✓	✓	✓
10	MicroMegas V.1		Pre-mix Ar/C ₄ H ₁₀	✓	✓	N/A	N/A	N/A



Detector Support Group

Weekly Report, 2016-05-25

11		Micromegas V.2	Mix Ar/C ₄ H ₁₀	✓	✓	N/A	N/A	N/A
12		Forward Tagger	N ₂	✓	✓	N/A	N/A	N/A
13	TEDF	HTCC	N ₂	✓	✓	✓	✓	✓

Status: Work in progress.

II. Hall B Gas System: DC Hardware in hall (George, Marc, Mindy, Sahin, Anatoly)

Task: Install Gas System hardware.
 EDC: N/A (Depends on Hall B Engineering)
 Activity: None.
 Comments: George: *"I updated the DCGAS and LTCC gas system critical path documents. In both cases we are waiting for critical path items to be completed by Hall B Engineering before we can continue."*

Status: No progress.

III. Hall B Gas System: LTCC Hardware in hall (George, Marc, Mindy, Sahin, Anatoly)

Task: Install Gas System hardware.
 EDC: N/A (Depends on Hall B Engineering)
 Activity: LTCC instrumentation hardware done.
 Comments: George: *"I updated the DCGAS and LTCC gas system critical path documents. In both cases we are waiting for critical path items to be completed by Hall B Engineering before we can continue."*

Status: No progress.

IV. Hall B HDICE (Mary Ann, Peter, Amanda, Tyler, Mindy, Sahin)

Task: Fabricate RF box. Task includes draw fabrication drawing in AutoCAD, write drivers for DIO modules, and develop RF box test program review.
 EDC: N/A.
 Activity: Developed and tested LabVIEW code for read-back of RF Switching/Attenuation Unit attenuators and remote interlock. Completed RF & interlock cables for test station.

Comments: None
Status: Work in progress.



Detector Support Group

Weekly Report, 2016-05-25

V. Hall B HDICE (Peter, Amanda, Mary Ann, Tyler, Pablo.)

Task: Development and troubleshooting of HDice NMR programming.
EDC: 09/15/2016.
Activity: Corrected problem in NMR programming to allow negative fields.
Completed troubleshooting and repair of NMR field timing errors.
Comments: None
Status: Work in progress.

VI. Hall B RICH (Tyler, Amanda, Peter, Brian, Mary Ann, George, Mindy, Sahin, Marc, Anatoly)

Task: Development of specifications for RICH interlock system.
EDC: N/A.
Activity: Meeting with INFN. Reviewed the cooling system, N2 purge system, and interlocks.
Researched VESDA system and airflow sensors for interlocks.
Comments: None.
Status: Work in progress

VII. Hall D Solenoid (Pablo, Peter, Brian, Tyler, Amanda, Mary Ann, Marc)

Task: Repair and maintenance of Hall D solenoid magnet.
EDC: N/A
Activity: Troubleshooting and repair Coil 3 He return temperature sensor.
Troubleshooting of Solenoid coil 1 strain gauge.
Comments: None
Status: Completed

VIII. Hall D PLC Systems (Pablo, Peter, Brian, Tyler, Amanda, Mary Ann, Marc)

Task: Generate Allen Bradley report for the Start Counter/Hall Environment/HV Reset Controls PLC system.
EDC: 06/24/2016
Activity: Generated report and revised the sequence for this system.
Compared documentation layouts for PLC.
Comments: None
Status: Work in progress



Detector Support Group

Weekly Report, 2016-05-25

Antonioli, Mary Ann

Hall B

HDice

- Tested LabVIEW code for RF Switching/Attenuation Unit on test stand, with Pete.
 - * “Read Attenuator A”, “Read Attenuator B”, “Read remote interlock”.
 - * Troubleshoot problems. Two causes: reverse logic in one module type and not enough bits to display dB.
 - * Changes made, re-tested, and now OK.

DSG

- Imported into InDesign and formatted Pablo’s note on Hall D PLC system.
 - * Began editing.
 - * Re-formatted and edited four of six tables.
- Compiled, formatted, and edited weekly report.
- Changed website photo and archived old photo.

Arslan, Sahin

Vacation

Bonneau, Peter

Hall B

HDice

- Troubleshooting NMR program errors.
 - * Fixed NMR negative center field problem (in LabVIEW 2015). Program now allows user to use both positive and negative fields during NMR runs.
 - * Fixed NMR problem (In LabVIEW 2015) “where it’s only understandable for range =300 and $T_{up} / T_{down} = 31$ sec”. Program was not calculating ramp rates correctly for Oxford power supply.
 - * Tested $T_{up}=T_{down}$ range from 15–300 s.
 - * Documented procedure for code fixes.
- Met with Xiangdong Wei regarding HDice NMR work.
 - * Reviewed and demonstrated fixes on NMR test station for negative center field problem and ramp rate issues.
 - * Xiangdong requested for range to be expanded from 15 to 10 s for minimum $T_{up}=T_{down}$ value.
- Worked with MaryAnn on the software development for ICP-CON DIO modules.
 - * Testing and troubleshooting of VIs for readback of “A” and “B” attenuators.
 - * Tested remote interlock read-back VI.

SVT

- Monitored SVT Hardware Interlock System on a daily basis.

RICH

- Researched slow controls sensors for interlock system.



Detector Support Group

Weekly Report, 2016-05-25

- * Reviewed specifications for VESDA smoke detection systems.
- * Researched possible CRio interfaces for smoke detection systems.
- * A daily meeting was held on instrumentation and tasks.

Hall D

- Due to a facilities-chilled water trip overnight, the chillers for the BCAL and FDC tripped.
 - * Chillers were reset in the morning.
 - * Alarms will be set up to send text messages when this occurs.
- Monitored Hall D slow control systems on a daily basis.

Campero, Pablo

Hall B

HDICE

- Solved problems with Mercury iPS power supply with Peter.
 - * Entered in Engineering Mode and added new values for the LRMF Lead Rate, Magnet Field. The default value (0.1 A/min) was changed.
 - * Monitored the new speed ramp rate (A/min) for current on home page screen of power supply; it was corrected.
- Began to read/write to Mercury iPS power supply assisted by Tyler and Amanda.
 - * Set up USB interface connection between HdicePC1 and iPS power supply.
 - * Downloaded and installed driver for USB communication.
 - * Wrote LabVIEW code to test communication.
 - * Generated sub-Vis for main SCPI commands.

RICH

- Visually inspected aerogel with Tyler and Amanda.
 - * Verified amount and state of the aerogel.
 - * Took pictures of each side, checked for imperfections, documented information, and stored in gowning room dry box.
 - * Sent inspection information to Valery and all concerned.
- Received mirrors and moved to small clean room.

Hall D

Slow Controls

- Met with Nick concerning task list for solenoid controls.
 - * Worked with Tyler and Amanda on Coil 3 He return temperature sporadic signal. The leads were changed from the redundant sensor location to the main sensor location; all located in terminal TS-LCP2 C3-6 at control rack.
 - * Checked the connections for the cable that was swapped. The problem seems to be solved, but needs monitoring.
 - * Entered logbook # 3406170, explaining solution.
- Assisted with problem with Strain Gauge Coil 1, which had loose connection.
 - * Sent e-mail to Scot requesting wiring diagram since label on cable was not clear.
 - * Checked signal on MYA viewer.



Detector Support Group

Weekly Report, 2016-05-25

Detector

- Review in progress of Environment/HV Reset/ Start Counter Control PLC system.
 - * Added information extracted from generated Allen Bradley report and revised programs and sequence for system.
 - * Compared with spreadsheet layouts that already exist.

DSG

- Troubleshooting FT-View 7.0 on DSGPLC1 computer.
 - * Sent request for technical support concerning error (SQL server 2008).
- Tested cRIO test station in 121C with Tyler and Amanda.
 - * Became familiar with hardware and software components of NI control systems.
 - * Tested temperature and humidity sensor connections on cRIO modules.
- Updated photos folder on M Drive with pictures taken in Hall D.

Eng. Brian

Hall B

SVT

- Performed software updates on SVTINTERLOCKS computer while SVT was powered down.
 - * Tried to get cRIO to communicate directly to Mpod to record current in sub-zero test.
 - * The net-snmp package from NI was too old (doesn't support extended precision output option, so can't read HV current); nightly releases didn't compile.
 - * Solution was to use SSH to run snmpget command on svtsystem1 to get HV current.
- Added HTSB and HV currents to SQLite logging on cRIO.
- Altered logic on temporary cRIO for SVT MFC to only write set point when less than value MFC can flow.
 - * Done to work around a limitation with cRIO-9075 vs cRIO-9035; the 9075 can't run embedded UIs so have to use shared variables as controls.
- Made plots for sensor data for sub-zero test.

Gas System

- Testing using HTSB without a separate power supply, using AO + AI module.
 - * Working.

Hoebel, Amanda

Hall B

RICH

- Assisted Tyler and Pablo with transporting mirrors to clean room.
- Checked 10 aerogel blocks for impurities, with Tyler and Pablo.
 - * Most had small chips and cracks. Two had significant chips.

HDice

- Troubleshot LabVIEW driver “*IDN?” command for Mercury iPS.



Detector Support Group

Weekly Report, 2016-05-25

- * IDN command gave no response; solution was selecting “\ Codes Display” on string menu.

Hall D

Magnet

- Assisted Pablo in swapping leads from redundant sensor location to main sensor location in terminal TS-LCP2 C3-6 at control rack.
- Assisted Pablo and Tyler in locating source of noise possibly not fixed by relocating redundant sensor leads.
 - * Checked MYA viewer for spikes in signal.
 - * Problem seemed to be fixed until noticed a new problem. Strain gauge signal on Coil 1 had heavy noise, a possible result from attempting to locate noise in sensor leads.
- Assisted Pablo, Tyler, and Nick in locating source of Coil 1 strain gauge issue.
 - * Monitored MYA viewer for spikes in signal.
 - * Strain gauge connection was found to be loose at coil.
- Wrote paper on voltage taps insert and query program.

DSG

Safety

- Studied for and took ODH 1 training.
- Studied for and took Rad Worker 1 training.

Jacobs, George

Hall B

DC

- Set up test stand gas supply with MKS 647 to mix 10% CO₂ in Ar.
- Discussions with Saptarshi about ASME storage tank relief valves and other pressure system considerations.

MVT

- Set up test stand gas supply with MKS 647 to mix 10% Isobutane in Argon.

HTCC

- Discussions with Youri S. on changing gas to CO₂.
 - * Need to purchase CO₂ press regulator and CO₂ dewars.
 - * Youri S. will clear purchases with Volker B.

RICH

- Created spreadsheet with components, part numbers, costs, for cooling circuit electronics.
 - * Updated with higher flow meters and transducers.
- Created spreadsheet with components, part numbers, costs, for N₂ purge circuit.
 - * Updated with higher flow meters and transducers.
- Created AutoCAD drawing of cooling circuit electronics.
 - * Updated with new flow specifications.
- Created AutoCAD drawing of aerogel N₂ purge circuit.
 - * Updated with new flow specifications.
- Discussions with Saptarshi on cooling circuit pressure systems electronics.



Detector Support Group

Weekly Report, 2016-05-25

- Participated in telephone meeting (new higher flow specs for both the N2 purge and air cooling circuits).

Misc

- Searched for missing Helmholtz coils to use for testing PMTs ends.
 - ★ Coils were recycled some time in 2015.

DSG

Safety

- Quarterly safety walk-through of bldg. 96B.

Leffel, Mindy

Hall B

HDICE

- RF Switching/Attenuation Unit
 - ★ Completed termination of replacement cables: one BNC – N and two N – N.
 - ★ Started prepping the nine internal cables for second unit.
 - ★ Terminated one end of two eight foot cables with SMA plugs.
 - ★ Terminated remote interlock test cable with a circular plug connector.

FT-Cal (Forward Tagger- Calorimeter)


- Worked with members of INFN.
 - ★ Removed and replaced surface mount connector on preamplifier motherboard.
 - ★ Removed one capacitor and one resistor from 40 preamplifiers, to reduce gain.

Lemon, Tyler

Hall B

RICH

- Visually inspected aerogel tiles with Amanda and Pablo.
 - ★ Received shipment of 10 tiles on 5/19.
 - ★ Photographed and checked each tile for cracks, air bubbles, and chips.
 - ★ See photo below of tile 3 with crack.





Detector Support Group

Weekly Report, 2016-05-25

- Attended INFN-DSG phone meeting.
 - ★ Discussed information about the cooling system, N₂ purge system, and interlocks for the review and the plan of action for upcoming tasks.
- Created and updated overall task list for detector.
- Stored mirrors in EEL 121b cleanroom with Pablo and Amanda.
 - ★ Wrapped box with plastic wrap to make cleanroom-safe.
- Researched scales for aerogel testing.
 - ★ Sent specs and quote for scale that meets requested specs to INFN group.
- Researched VESDA system and airflow sensors for interlocks.

Hall D

Magnet

- Troubleshooting of sporadic signal for Coil 3 He return with Pablo and Amanda.
 - ★ Moved He return temperature sensor wires from redundant spare terminal block to main sensor terminal block.
 - ★ Checked connections on Coil 3 to see if bad connections caused sporadic signal.
 - ★ Traced sensor cabling from Coil 3 connection to Lakeshore to see if bad cables caused sporadic signal.
- Troubleshooting of Coil 1 strain gauge signal error.
 - ★ Noted jump in Coil 1 strain gauge at the time we were checking the He return connection on Coil 3.
 - ★ Traced error to loose connection for strain gauge on Coil 1.
 - ★ Made logbook entry to note strain gauge signal error; contacted Scot Spiegel for more information.

DSG

MPOD Test Station

- Guided Anatoly's work in performing voltage test for MPOD LV card 3.

McMullen, Marc

Hall B

Gas System

- DC Gas
 - ★ Updated the mix gas system to be controlled via the total flow and CO₂ percentage of the mix. The CPU usage of the Gas Shed cRIO is ~30%, which is much improved.
 - ★ Continued writing code to display and control the MKS 647. The method of setting up mass flow controllers using the current VI differs from setting up control at the 647; the current VI sets flow by using a percentage of the full scale versus entering a set point.
- HTCC
 - ★ Updated GUI, which now has separate graphic displays for temperature/humidity and ambient/differential pressure.
 - ★ Monitored gas flow.



Detector Support Group

Weekly Report, 2016-05-25

- RICH
 - * Participated in conference call.
 - Forwarded Jlab laser safety guidelines. For testing, a class 2 laser may be used without further laser safety considerations or documentation, however this should be noted in the B-List.
 - Measuring humidity in the electronics below 0.002% would need a sensor on the order of the Easidew online hygrometer (the same used by the HTCC and DC gas system), with an approximate cost of \$2K per sensor/readout.

DSG

Safety

- Accompanied EH&S Safety Warden manager to identify areas of the building which had not been upgraded to the VIOP phones.

Sitnikov, Anatoly

Hall B

SVT

- Completed calibration of Mpod LV card #3 voltage test. Began current test.
 - * Voltage test–1296 measurements.
 - * Current test–168 measurements.