



# Detector Support Group

## Weekly Report, 2017-03-29

### State of Play

#### Announcement

- Sahin Arslan will be leaving for USAF Reserve duty.
  - \* Sahin will be absent from the lab from 04/10/2017 to 08/28/2017.
  - \* Sahin, **good luck and God bless.**
- In Sahin's absence:
  - \* Marc McMullen and George Jacobs will be responsible for change out of gas cylinders, for which DSG is responsible.
  - \* George, as Master Rigger, will develop lift plans and supervise lifts, for which DSG is responsible.
  - \* Mindy Leffel will take over moves of equipment and accessories with pallet jack and forklift, on an as needed basis.

#### HDice

- Test program to measure Lock-in Amplifier external trigger efficiency developed.

#### SVT

- User interface computer, cRIO system software, and interlock system program upgraded to LabVIEW 2016.
- CSS screens running from clon machines have been up for nearly a week, which is a big improvement over version from ACC machines.

#### RICH

- Detector shell rotated back to horizontal position.
- Electronics panel reworked to accommodate connectors.
- Quotes received for stiffner assembly.

#### FT

- "Health" status routines for cRIO developed for interlock system.
  - \* Routines debugged and integrated into real-time and user interface programs.



# Detector Support Group

## Weekly Report, 2017-03-29

### Antonioli, Mary Ann

- Continued working on **HDice** NMR software flowchart.
- Continued writing **RICH** interlock LabVIEW code — two global subVIs and initialization of variables.
  - \* Tested and debugged.
  - \* Loaded SD card code from Peter's project, reviewed, and tested.
  - \* Discussed configuration file and communications loop with Peter.
- Compiled, edited, and formatted weekly report.
- Changed website photo.

### Arslan, Sahin

- Replaced SVT N<sub>2</sub> bottle and inventoried N<sub>2</sub> gas bottles.
- #### RICH
- Continued working on detector assembly, fabricating, assembling, and modifying
  - Assisted with fit test of electronic panel on detector and necessary adjustment and modifications
  - With Mindy and Tyler, drilled 16 missing HV connector holes on carbon fiber electronic panel
  - Reduced width of gasket on front panel per Sandro's request.
  - Assisted in removal of two front panels, top bar, installed back bottom bar, and rotated assembly back to horizontal, using winch and gantry.
  - Fabricated ½" aluminum plate and drilled holes, to be used to fill gap between structure and detector.
  - With Mindy, cleaned up semi clean room and relocated compressor and air tank to designated area. Transferred basket of DC signal and LV cables to ESB.

### Bonneau, Peter

- Upgraded **SVT** user interface computer, cRIO system software, and interlock system program to LabVIEW 2016.
- Developed cRIO health status routines for **Forward Tagger** interlock system, debugged, and integrated into real-time and user interface programs.

#### RICH

- Met with Marco Mirazita regarding interlock system temperature and humidity sensors.
  - \* Marco thought sensor boards would fit into detector.
  - \* Sent information to mailing list on board connectors, for possible integration into patch panel.
- Worked with Mary Ann on hardware interlock code.
  - \* Discussed interlock control subroutine integration into real-time main program. Interlock-enable shared variable was expanded to include entire array depth.
  - \* Solved configuration issues with NI9205 module, which was reprogrammed for differential mode operation.
  - \* Debugged and corrected indexing problem that was causing incorrect data in interlock subroutine.



# Detector Support Group

## Weekly Report, 2017-03-29

- \* Discussed program messaging and its role in interlock user interface and real-time main.

### HDice

- Developed test program to measure Lock-in Amplifier external trigger efficiency.
  - \* Program used cRIO in FPGA mode programmed as scaler to measure actual trigger count vs. buffer counter in lock-in amplifier.
  - \* Lock-in amplifier trigger efficiency dropped below 100% at frequencies above 425 Hz.
  - \* Discussed test program with Amanda.
  - \* The NMR test station is being reassembled in EEL lab in preparation for synchronization testing.
- Held daily meeting on Hall D status and EPICS controls monitoring.
  - \* Humidity levels in BCAL have remained low after cooling duct repair.

### Campero, Pablo

- For RICH assembly, contributed to:
  - \* Removal of detector front panel.
  - \* Re-assembly of lower horizontal bar with foot for detector frame.
  - \* Rotation of frame structure to horizontal position, for ease of exit window installation.
- Monitored and analyzed logbook entries and EPICs screens for Hall D daily.
  - \* FDC HV channels were turned off.
  - \* Upstream BCAL PLC has communication issues with EPICs.
- Worked on VME Test Station
  - \* Wrote LabVIEW program to read out RTD signals from V450 ADC board, connected RTD temperature sensor, and tested.
- Wrote LabVIEW program to test ADC channels on V450 board.
  - \* Used voltage source to test inputs to channel 0 at 0–5 V range and 16 bits resolution.
  - \* Performed 1000 measurements at 1 V steps, from 0 through 5 V.

### Eng. Brian

- Reconnected SFL3N cRIO with Marc after gas panel was reinstalled. DC read-only indicators added to stand-alone GUI.
- 3D printed panel templates for RICH received.

### SVT

- Replacement chiller is broken. Attempted to connect original chiller (which already was repaired) but no plugs in EEL/124. Working with Fast Electronics to figure out how to power it.



# Detector Support Group


## Weekly Report, 2017-03-29

- CSS screens running from clon machines have been up for nearly a week, which is a big improvement over version from ACC machines.

### Hoebel, Amanda

#### RICH

- Took pictures of electronics panel frame installation for DSG website.
- Attended talk for collaboration meeting.
- Tested PLC analog input module with voltage source for varying voltages.
  - \* Tested eight channels.
  - \* Created graphs of voltages.
  - \* Relationship is linear.



Graph showing linear relationship between PLC voltage set and readback for Ch 0.

### Jacobs, George

#### GAS Systems

- Connected gas lines to DC solenoid panel.
- Determined that there is a significant leak in R1-2 DC gas exhaust manifold on Torus.
- Labeled DC system manual valves with numbered brass tags.



## Detector Support Group

### Weekly Report, 2017-03-29

- Wired DC Magnahelic pressure transducers, verified proper read back in gas shed and EPICS.
- Pre-job planning for N<sub>2</sub> gas supply work.
- Discussed pressure testing gas systems with Dave Kashy.

#### Leffel, Mindy

##### RICH

- Continued fabricating HTSBs.
- Contributed to rotating shell back to horizontal.
- Worked with Sahin to organize curtain room and relocate compressor and tank.
- Worked on carbon fiber electronic panel.
  - ★ Contributed to cutting missing slots for HV connectors.
  - ★ Filed slots that were too small.
  - ★ Worked with Mary Ann to verify connector fit after filing.


#### Lemon, Tyler

- Contributed to RICH assembly.
  - ★ Removed detector front panel.
  - ★ Replaced bottom horizontal bar of assembly structure.
  - ★ Removed top horizontal bar of assembly structure.
  - ★ Assisted with rotation of detector back to horizontal.
- Monitored logbook and EPICS on daily basis.
  - ★ Noted entry stating LCW leak repairs in progress for Solenoid power supply.
- Completed first version of LabVIEW test program for NI-9219 ADC modules, measuring voltage from Krohn-Hite Model 523 Precision DC Source using NI-9219 ADC module at user-specified ranges.
  - ★ Measures voltage on all four ADC channels.
  - ★ Available input ranges:  $\pm 60$  V,  $\pm 15$  V,  $\pm 4$  V,  $\pm 1$  V,  $\pm 125$  mV.
  - ★ Uses updated Krohn-Hite LabVIEW 2016 drivers.
  - ★ Writes data to .txt file.
- Wrote Python program to generate histograms from ADC module test results.
  - ★ Test parameters: 1000 samples per channel; 4 V ADC input range; 1 V input signal from Krohn-Hite.
  - ★ Below: Histograms generated for each channel.



# Detector Support Group

## Weekly Report, 2017-03-29



Histograms generated in Python using resulting data from NI-9219 ADC module test. Vertical, red, dashed line indicates mean of 1000 samples taken for each channel.

### McMullen, Marc

#### Gas System

- Continued modifying gas system GUI to work with new gas mixing VI through networked variables. Completed mix calibration subVI.
- Reconnected pressure transducers and valve drivers to interface chassis on SFL3.
- With Brian, debugged some Gas Shed signals; manifold pressure, return flow, and moisture signals were not updating.

#### RICH

- Met with Bob Miller to discuss stiffener quote received from Precise.
  - ★ Suggested that we get more quotes, and that quotes will be random in amount.
  - ★ Hall B Mechanical would have needed a lot of overhead to fabricate assembly.
- Met with GandR Machinery to discuss fabrication of stiffener assembly.
  - ★ Received quote. INFN is waiting for more quotes before final decision.
- Started Electronics Installation and Testing TOSP.
  - ★ Reviewed procedure and wrote THA.
  - ★ Contacted Valery to clarify testing to be done in EEL.
  - ★ Received installation procedure from Marco.
- Completed monthly safety walk-through.