



Detector Support Group

Weekly Report, 2018-01-24

Summary

Hall B Magnets

- Torus and Solenoid monitored on a daily basis via EPICS and logbooks.
 - ★ Noise on VCL B VT21 caused controlled ramp interlock trips while the magnet power supply was turned on and the current set at 0 A.
 - Condition added to Solenoid PLC program requiring absolute current to be greater than 10 [A] before interlock becomes active.
 - ★ Torus axial and vertical strain gauges analyzed.
 - Eight strain gauges monitor strain in the vertical upstream and downstream supports.
 - Six strain gauges monitor strain on the axial supports in coils B, D and F.
 - ★ Table generated to monitor Torus strain gauge interactions with Torus and Solenoid magnetic fields.
 - ★ Solenoid fast-dump on January 24, 2018 possibly caused by coil shifts.

SVT

- Trip delay timers and signal averaging added into SVT Hardware Interlock System control logic.
- New A40 chiller tested.
 - ★ When pump speed is set to “auto”, A40 chiller reduces flow in bath when temperature is under 0 °C.
 - ★ Pump speed set to “high” to prevent decreases in flow at low temperatures.
- RTD ordered to measure temperature of chilled nitrogen gas
- Module currents dropped by ~400 μ A after implementation of new chilled nitrogen system.

RICH

- Diagram of second cRIO chassis layout generated to note part numbers and screw sizes.
- Power wiring diagram for second cRIO generated in Visio.
- Hole to mount the AC connector in second cRIO chassis machined.
- Second cRIO chassis wiring started.
- RICH-N2-valve-panel-REV P&I diagram and components list updated
- Additional components ordered for RICH N₂ valve panel upgrade.

RTPC

- Cost estimate for controls equipment and hardware prepared.
- Meeting held with RTPC representatives to discuss detector's gas system:
 - ★ Gas system cost estimate will be forwarded to RTPC detector management.
 - ★ Advance notice requested on procurement of components.
 - ★ RTPC group considering using a mixing system to mix helium and CO₂ instead of premix bottles.



Detector Support Group

Weekly Report, 2018-01-24

HDice

- Test station for Rack #1 hardware and software development debugged.
 - ★ NMR program would not reliably connect with instrumentation, causing the program to freeze.
 - Cause of problem was intermittent GPIB communication faults between the NMR computer and instrumentation; replacement of the GPIB controller resolved issue.
 - ★ NMR program would halt during scan initialization and continuously loop on a liquid helium level sensor fault.
 - NMR program revised to bypass liquid helium level sensor check and helium temperature check during scan initialization when the respective sensors are disabled.
- Redesign of Rack #1 RF distribution and attenuation control.
 - ★ Redesign will allow display of RF Box settings on its front panel display and computer read-back of the actual settings in the control computer.
- All power and control wiring of RF Box #1 completed.
- Isolation brackets cut for the second rack.

LTCC

- C₄F₁₀ gas flow started in LTCC S5
- Overpressure bubbler installed for LTCC S5.
- LTCC-SingleSector-piping.pdf diagram modified to show both bubblers.

MVT

- As of January 22, 2018, there are six bottles of premix left,
 - ★ Delivery of 20 more premix bottles expected in early February.

cRIO Test Station

- Options to run test program from the local PC on a user interface by utilizing LabVIEW's messaging features investigated.
 - ★ Running test program on local PC would allow for easier access to results.

MPOD Test Station

- Drivers developed in LabVIEW for Keithley 2002 multimeter to set multimeter's measurement settings for MPOD tests.
- Programs developed to acquire data from Keithley multimeter in two ways:
 - ★ Scan all channels at once: allows tests to verify output of MPOD is only enabled for the set channel.
 - ★ Measure single channel: allows for fast acquisition (100 samples in ~10 seconds) of measurements for a single channel.
- Developed version of all drivers and programs to work with either Prologix GPIB-USB controller or NI GPIB interface.



Detector Support Group

Weekly Report, 2018-01-24

Antonioli, Mary Ann

- Completed all power and control wiring of HDice RF box 1.
 - * RF wiring remains, to be completed by Mindy.
- Drew RICH cRIO power wiring diagram in Visio.

Bonneau, Peter

HDice

- Debugged test station for Rack #1 hardware and software development.
 - * NMR program would not reliably connect with instrumentation, causing the program to freeze.
 - Cause of problem was intermittent GPIB communication faults between the NMR computer and the RF signal generator, lock-in amplifier, and Oxford power supply.
 - Replacement of the GPIB controller resolved the issue.
 - * NMR program would halt during scan initialization and continuously loop on a LHe level sensor fault.
 - NMR program revised to bypass liquid helium level sensor check and helium temperature check during scan initialization when the respective sensors are disabled.
- Worked with Mary Ann on the upgrade of Rack #1 RF distribution and attenuation control.
 - * Redesign will allow the display of the RF box instrumentation settings on the front panel display and computer read-back of the actual settings in the control computer.

SVT

- Worked with Pablo on the SVT Hardware Interlock System upgrades.
 - * Discussed implementation of interlock trip sub-routines and the addition of the delay trip timers and signal averaging option into the interlock control logic.
 - * Added temperature and humidity sensors to the DSG cRIO Development System for the test and debug of the SVT interlock system upgrade.

Magnets

- Met with Amanda, Pablo, and Tyler regarding issues encountered with the Torus and Solenoid magnets during the engineering run.
 - * While the magnet power supply was turned on and the current set at 0 A, noise on VCL B VT21 was causing controlled ramp interlock trips.
 - A condition was added in the PLC program requiring the current to be > 10A before this interlock becomes active.
- Worked with Mindy on the design and layout of power distribution system for the new DSG cRIO Development System chassis.



Detector Support Group

Weekly Report, 2018-01-24

Campero, Pablo

Magnets

- Analyzed Torus axial and vertical strain gauges locations with Amrit, Peter, Tyler and Amanda.
 - ★ Eight strain gauges are distributed in the vertical upstream and downstream supports.
 - ★ Six strain gauges are set on the axial supports in coils B, D and F.
- Generated table to monitor how the Torus strain gauges values are affected by Torus and Solenoid magnetic field.
- Monitored Solenoid and Torus on a daily basis through EPICS screens and logbooks.
- Completed modifications to upgrade SVT Hardware Interlocks Real-Time LabVIEW program.
 - ★ Added averaging and trip delay timers for dew point, coolant flow, coolant temperature, and coolant leak detection interlocks.
 - ★ Configured upgraded SVT LabVIEW program to run on developmental cRIO system (DSGCRIODEV2).
 - Tested averaging upgrade for temperature signals.
- Investigated options to run cRIO Test Station from the local PC on a user interface.
 - ★ Consulted National Instrument documentation to learn about Queued Message Handler for potential implementation in the current cRIO Test Station LabVIEW program.

Eng. Brian

SVT

- Testing new A40 chiller: <https://logbooks.jlab.org/entry/3519131>
- Researched and ordered RTD to measure temperature of chilled N2 gas
- Met with RTPC collaborators to discuss gas system components
- Ordered spare/replacement PXI controller
- Upgraded Mac minis in EEL/231 to OS 10.12



Detector Support Group

Weekly Report, 2018-01-24

Hoebel, Amanda

Magnet

- Monitored Torus and Solenoid via EPICS and logbooks.
- Discussed solenoid fast-dump.
 - ★ Fast dump possibly caused by coil shifts.
- Compared currents in SVT modules before and after new cooling.
 - ★ Currents dropped by ~400 μ A after cooling.
- Reviewed FT LabVIEW interlocks program.
- Wrote note on DC TCUs.

Jacobs, George

RICH

- Ordered additional components for RICH N₂ valve panel replacement
- Created updated RICH-N2-valve-panel-REV P&I diagram and spreadsheet components list

LTCC

- Started C₄F₁₀ gas flow in LTCC S5
- Installed overpressure bubbler for LTCC S5 at original location
- Modified LTCC-SingleSector-piping.pdf diagram showing both bubblers

Gas Systems

- Contacted vendor AirGas about bulk liquid argon delivery due to low tank level
- Ordered CO₂ for DC and HTCC, 4 dewars
- Met to discuss RTPC gas system with collaborators.
- Completed MGT105 Training – Ethics for Supervisors

Leffel, Mindy

RICH

- For second cRIO chassis:
 - ★ Discussed wiring diagram with Peter.
 - ★ Started wiring.
- Created diagram of second cRIO chassis layout
 - ★ Diagram includes part numbers and screw sizes.

HDICE

- Cut isolation brackets for the second rack.



Detector Support Group

Weekly Report, 2018-01-24

Lemon, Tyler

- Monitored Hall B Magnets via EPICS and logbooks and discussed status on a daily basis with Peter, Pablo, and Amanda.

MPOD Test Station

- Developed drivers in LabVIEW for Keithley 2002 multimeter.
 - * Drivers developed to:
 - Verify scan card is installed in multimeter
 - Set which channels to scan.
 - Set all channels to read DC voltage.
 - Configure and initiate scan of selected channels.
 - Repeat scan.
 - Take single measurement from multimeter.
 - Parse string output of multimeter extract voltage measurement.
 - Calculate mean and standard deviation from measurement arrays.
- Used drivers to develop programs acquire data from Keithley multimeter in two methods:
 - * Scan all channels at once.
 - Will allow tests to verify output of MPOD is only enabled for the set channel.
 - * Measure single channel.
 - Allows for fast acquisition (100 samples in ~10 seconds) of measurements for a single channel.
- Developed version of all drivers and programs to work with either Prologix GPIB-USB controller or NI GPIB interface.

McMullen, Marc

MVT

- Six bottles of premix left, As of January 22, 2018.
 - * Delivery of 20 more premix bottles expected in early February.

LTCC

- LTCC filling with C₄F₁₀
 - * Pressure at 0.77 [inH₂O] as of January 23, 2018.

RICH

- Machined a hole to mount the AC connector in second cRIO chassis.

RTPC

- Prepared cost estimate for controls equipment.
- Met with RTPC representatives.
 - * Hardware and controls cost estimate will be forwarded to the detector management.
 - * Requested advance notice on procurement of components.
 - * RTPC group is considering using a mixing system to mix helium and CO₂ instead of premix.