



# Detector Support Group

## Weekly Report, 2018-04-11

### Summary

#### Hall B Magnets

- Torus had controlled ramp down on 4/5/2018 due to loss of communication with FastDAQ cRIO.
  - \* cRIO debugged and successfully rebooted using remote serial connection.
  - \* Ramp down was stopped; Torus ramped back to negative full field.
- Torus had controlled ramp down on 4/10/2018 due to helium vent to atmosphere caused by increase in helium return pressure.
  - \* Vent to atmosphere stopped once helium return pressure returned to normal, allowing ramp down to be halted.
- Solenoid had fast dump on 4/9/2018 because of trip on Quench Detector #1 Channel 1.
  - \* No FastDAQ data available due to error in EPICS archiving.
- External cron job added to monitor CPU and memory of both FastDAQ cRIOs.
  - \* Monitoring will help determine whether CPU-usage error or memory error is cause of unrecoverable FastDAQ cRIO failures.
- Console output adapter cable reinstalled on Torus LV cRIO.
  - \* Original adapter was moved to Solenoid FastDAQ cRIO when it was replaced on 4/1/2018.

#### SVT

- Patch panel board used for humidity and temperature sensors received.
  - \* Populating of patch panel boards started.
- Surface mount RTD wiring tested in a four-wire configuration on patch panel board.
- Operating system and drivers loaded onto replacement Hardware Interlock cRIO.
- Redesign of HTSB completed to use the surface mount RTD.

#### DC

- Gas switched to 90%-Ar/10%-CO<sub>2</sub> standard to monitor TCU1 voltage.

#### HDice

- SubVI library developed to calculate data acquisition rates for synchronization.
  - \* Based on the duration of the NMR scan, the developed subVIs maximize the number of data acquisition points and DAQ rate using the current shunt's settings.
  - \* Current shunt's DAQ settings used rather than lock-in amplifier's as lock-in amplifier's external triggering rate is limited to 300 Hz in synchronous operation.
- Error-checking routine to scan data length vs. acquisition rate completed.



# Detector Support Group

## Weekly Report, 2018-04-11

### LTCC

- C<sub>4</sub>F<sub>10</sub> quote requested and received from F2 Chemicals.
  - \* 500 kg in stock at \$135 per kg (\$67,500 total).
  - \* New price of \$260 per kg for future purchases once 500 kg on-hand stock is gone.
  - \* At least six month lead time on any order.
- Quote requested for C<sub>4</sub>F<sub>8</sub>O from Praxair and 3M.
  - \* C<sub>4</sub>F<sub>8</sub>O is no longer available.
- LTCC flows show that Sector 6 leakage has increased over time.

LTCC Sector	Average of Daily Leakage Since November 8, 2017 [L]	Sector Status
1	—	Uninstalled
2	38.91	Flowing nitrogen
3	4.34	Bypassed
4	—	Uninstalled
5	33.65	Flowing C <sub>4</sub> F <sub>10</sub>
6	587.17	Flowing nitrogen

### cRIO Test Stand

- Integral nonlinearity automatic test updated to use calculated full-scale voltage.
- Missing code test for automatic mode developed and successfully tested.
- Automatic mode for full set of tests for 9207 ADC module debugged.
  - \* When full set was run, integral nonlinearity test showed no results.
  - \* Adding a delay before start of integral nonlinearity test resolved error.
- Set-up and wiring defined for current input test of NI-9207 ADC module.
  - \* NI-9265 analog output module will be used as current source.

### EEL 124 cleanroom

- Moisture content of concrete floor is measured to be ~90%.
  - \* Moisture content determines type of epoxy needed for floor repairs.

### Workers Safety Committee

- Mike Maier noted that workload will be increasing across the lab and supervisors should be asking, “Can the work be done safely in the time allotted?”
- Questions were brought up as to whether training is needed to use breaker panels.



# Detector Support Group

## Weekly Report, 2018-04-11

### Antonioli, Mary Ann

- Updated [RICH](#) N<sub>2</sub> system drawing.

### cRIO Test Stand

- Updated integral nonlinearity automatic mode test to use full-scale voltage calculated for previous tests.
- Developed and successfully tested missing code test for automatic mode.
  - ★ Many channels failed.
- Added a status message for each test in automatic mode.
- Tested and debugged automatic mode for full set of 9207 tests
  - ★ Program failed; integral nonlinearity test showed no results.
  - ★ Adding a wait time before integral nonlinearity test resolved error.
  - ★ Successfully ran a shortened test with less samples and less channels.
- Made Visio wiring diagram of module setup for 9207 testing.
  
- Attended Workers Safety Committee meeting.
  - ★ According to Mike Maier, workload will be increasing across the lab and supervisors should be asking, “Can the work be done safely in the time allotted?”
  - ★ Question brought up of whether or not training needed to use breaker panels.

### Bonneau, Peter

#### HDice

- Developed subVI library to calculate data acquisition rates for synchronization.
  - ★ Subroutines maximize the number of data acquisition points and DAQ rate depending on the length of the entire NMR scan.
    - Subroutines based on the current shunt DAQ rate settings rather than the lock-in amplifier.
  - ★ Maximum DAQ rate is lower than non-synchronized NMR due to the lock-in amplifier external triggering limitation (~ < 300 Hz).
  - ★ Started testing and debugging of the DAQ library at various acquisition rates and scan lengths.
- Development continued for data array error-checking routines.
  - ★ Completed error-checking routine to scan array data length vs. acquisition rate.
- Completed assembly of current calibration system for check of CT-box current shunt and Oxford power supply set and read-back settings.

#### SVT

- Loaded operating system and drivers onto SVT Hardware Interlock System’s replacement cRIO model 9035.

#### Hall D

- Held meetings on Hall D status and EPICS controls monitoring.

### Campero, Pablo



# Detector Support Group

## Weekly Report, 2018-04-11

### Magnets

- Torus had controlled ramp down on 4/5/2018 due to lost communication with FastDAQ cRIO.
  - ★ cRIO debugged using remote serial connection.
  - ★ Console output log indicated that the system was rebooted into safe mode.
  - ★ Rebooted FastDAQ cRIO; cRIO started without any problem
  - ★ Torus controlled ramp down was stopped and ramped back to negative full field.
- Solenoid Fast Dump on 04/09/2018
  - ★ Investigated causes for the dump and found that QD#1ch1 tripped first, but there was not FastDAQ data available
    - Data was not recorded due to software IOCs were not rebooted after the last rebooting of the FastDAQ cRIO.
  - ★ Found that SOE timestamps used to determine sequence of the trips were not totally correct. Time did not match time recorded in the EPICS archive.
- Created Magnets Health Status report for DSG weekly meeting.
- Switched DC gas to standard 90%-Ar/10-CO<sub>2</sub> mix to monitor TCU voltage for one week, with Marc, Tyler, and Amanda.
- For cRIO Test Station, set up defined for NI-9207 ADC module to test current inputs.
  - ★ For current source, an NI-9265 analog output module will be used.
  - ★ NI-9207 ADC input module will be used for current measurements.
  - ★ Determined wiring for the modules to be connected.

### Eng. Brian

- For SVT, tested surface mount SMT RTD wiring that Mindy did on a test board.
  - ★ RTD works for 4-wire resistance measurement using Keithley 2002.
- For Gas System, met with Marc to discuss upgrades to MFC power chassis

### Hall B Magnets

- Added external cronjob to monitor CPU and memory of both FastDAQ cRIOs.
- Torus FastDAQ cRIO got into safe mode causing a controlled ramp
  - ★ Reboot of cRIO fixed it.
  - ★ <https://logbooks.jlab.org/entry/3555317>
- Solenoid fast dumped because of QD1.
  - ★ <https://logbooks.jlab.org/entry/3557372>
  - ★ FastDAQ data was not available because of EPICS issue so details on voltage taps were unavailable.
- Reinstalled console output adapter cable on Torus LV cRIO.
  - ★ <https://logbooks.jlab.org/entry/3557384>
- Created first draft of Hall B cRIO training slides.

### Hoebel, Amanda



# Detector Support Group

## Weekly Report, 2018-04-11

### DC

- Switched gas to standard 90/10 mix to monitor TCU voltage for 1 week, with Marc, Tyler, and Pablo.

### Magnets

- Went over how to check SOE data and reset cRIO remotely for magnet off-hours support with Tyler and Pablo.
- Investigated controlled ramp-down of Torus on 04/05.
  - \* cRIO booted into safe mode, causing ramp-down.
- Worked on programming:
  - \* Reviewed arrays, lists, sets, matrices, and dictionaries in Python.
  - \* Learned vectors, matrices, and lists in R.
- Started SVT health status report.

### Jacobs, George

#### LTCC

- Monitored daily LTCC S5 single sector test detector pressure and gas usage.
  - \* Updated LTCC S5 single-sector test status power point.
- Discussed with Hall B the LTCC C<sub>4</sub>F<sub>10</sub> recovery system status and requirements for the path forward.
- Requested and received C<sub>4</sub>F<sub>10</sub> quote from F2 Chemicals.
  - \* 500 kg in stock at \$135 per kg.
  - \* New price of \$260 per kg for future purchases once 500 kg on-hand stock is gone.
- Requested quote for C<sub>4</sub>F<sub>8</sub>O from Praxair and 3M.
  - \* Both reply stating C<sub>4</sub>F<sub>8</sub>O is no longer available.

### Leffel, Mindy

#### Hall B

##### SVT

- Started populating patch panel boards.
  - \* Tested five boards for continuity
  - \* Soldered 25-pin D-sub connectors.

#### DSG

- Continued review for overhead crane training.

### Lemon, Tyler

- Revised RICH detector health report.

#### Hall B Magnets

- Recovered Torus FastDAQ cRIO from failure with Pablo, Amanda, and Brian.
  - \* On 4/5/2018, Torus FastDAQ cRIO stopped communicating to the Torus PLC, causing a controlled ramp down.
  - \* cRIO could not be connected to through NI-MAX or pinged, but could be communicated with through serial connection to terminal server.



# Detector Support Group

## Weekly Report, 2018-04-11

- \* Noted from terminal server log that cRIO had put itself into safe-mode, but reason why is unknown.
- \* cRIO was rebooted using terminal server, Torus FastDAQ program restarted and cRIO returned to normal operation.
- \* Controlled ramp down was able to be halted and the magnet ramped back to previous setting.
- Investigated cause controlled ramp down on 4/10/2018.
  - \* Cause of ramp down: an issue with ESR caused helium return pressure to increase and vent helium to atmosphere for long enough to cause a controlled ramp down.
    - If helium vents to atmosphere for 30 seconds, controlled ramp down is initiated.
    - Solenoid did not ramp down as it did not vent helium to atmosphere for the 30 seconds required for ramp down initiation.
  - \* Noted during investigation that Cryo-Sum interlock indicator for both Torus and Solenoid did not show status of helium vent to atmosphere in breakdown of summed interlocks.
    - Caused summation of Cryo interlocks to show as tripped without an explanation in the breakdown of the summation.
- Investigated cause of Solenoid's fast dump on 4/9/2018.
  - \* Fast dump triggered by QD#1:Ch1:lower.
  - \* Had issue during investigation with improper conversion of SOE timestamps.
    - Conversion program gave timestamp ~10 minutes later than time of dump.
- Investigated lack of FastDAQ data for Torus and Solenoid since 4/1/2018.
  - \* Noted during 4/9/2018 Solenoid investigation that no FastDAQ data had been archived since 4/1/2018.
  - \* Cause determined to be communication error between cRIO and IOC when cRIO is rebooted.
  - \* Fix is to reboot IOC if cRIO is rebooted.
  - \* Changes added to magnet energization procedure to confirm FastDAQ files are being written.
- Assisted with drilling of EEL 124 floor to determine moisture content of the concrete.
  - \* Moisture content of concrete will determine type of epoxy needed for floor repairs.
  - \* After moisture content is read, quote for floor repair will be generated.

### **McMullen, Marc**

#### **SVT**

- Completed redesign of HTSB.
  - \* The new design uses a 1206 surface mount RTD.
  - \* Mindy and Brian have tested the replacement temperature sensor.
- Received Patch Panel board #2 used to measure humidity and temperature.

#### **Gas System**

- Modified new MFC power chassis design per Brian's recommendations.



## Detector Support Group Weekly Report, 2018-04-11

- ★ Chassis will be reduced from a double DIN to a single DIN size.
- DC Mix TCU switched over to measure from the 10%-CO<sub>2</sub> standard.
- LTCC flows show that sector 6 leakage has increased over time.
  - ★ Sector 2 is still relatively leak tight.

LTCC Sector	Daily Average Since November 8, 2017 [L]	Sector Status
1	56.93	Uninstalled
2	38.91	Flowing nitrogen
3	4.34	Bypassed
4	10.96	Uninstalled
5	33.65	Flowing C <sub>4</sub> F <sub>10</sub>
6	587.17	Flowing nitrogen