

Weekly Report, 2018-06-20

Summary

Hall C

*

- HMS and SHMS Dipole field regulation investigated for use of NMR PT2026 in PLC routine.
 - * Found Flex I/O module for HMS in the detector, under the rack on the floor.
 - * Specs for Flex I/O adapters and Profibus modules revised.
 - Profibus modules are used to transfer data from serial RS232 to ControlNet in SHMS PLC systems.
 - * Commands that are sent to regulation-module RG2024 checked.
 - Commands are used to send and receive data from the NMR and PSU to the PLC.
 - PLC Dipole code sends separate commands to the RG2024 module to perform the field regulation.
 - The implementation of the new routine to perform the Dipole field regulation and NMR PT2026 unit will require modifications in several existent PLC programs and HMI screens.
 - SBC card set up and configured to communicate with NMR PT2026 unit.
 - * Debian Linux installed on SBC.
 - * IP address assigned (129.57.195.33) for the Hall C- DEV subnet.
 - VXI implementation was corrupt on NMR unit- bypassed with Python VXI11 driver. NMR can now communicate with SBC.
- Factory Talk View Studio v10 installed on DSGPLC1 and dsg-hallc-2 PCs to run HMI (.sed) files used for SHMS and HMS.
 - Incorrect software version used to open HMI files caused error.
 Error showed "unnamed displays".
 - * SHMS and HMS projects had to be opened in "grace period", since there is no available license to run more than 25 displays in FactoryTalk View SE.
 - * Mike Fowler informed on 6/21/18 the correct version of Factory Talk, version 8.
- Shutter controls and monitoring discussed with Joe Beaufait.
 - ★ For SHMS shutter:
 - Fully opened status gives 24V read-back.
 - Installed and fully closed, or uninstalled gives 0V read-back.
 - No way to distinguish between shutter "uninstalled" and shutter "installed and fully closed".
 - Current wiring only allows remote monitoring/controls via PLC to open shutter or see if shutter is open.
 - ★ Local controls in place for HMS shutter.
 - No actual wiring diagram exists for either shutter.
 - Wiring diagram is "in Joe's head".
 - ★ Implementation of shutter installation monitoring would require a wire loop.
 - Existing wire to shutter most likely does not have enough pins to support this wire-loop connection.
- Hall C 1756-IB16D diagnostic digital input module implemented in DSG's PLC test station for development of UPS monitoring.
 - * Relay card for small UPS will send a 24V signal to HMS I/O chassis digital input.
 - There are several spare diagnostic digital inputs for relay card output in the SHMS and HMS PLC systems.
 - * Also investigating how to use diagnostic input to sense a broken signal wire to potentially use relay as a short between input terminals without 24 V supply.



Weekly Report, 2018-06-20

RICH

- Air-cooling compressor powered on for electronics testing.
 - * Airflow 1 set to ~500 slm, airflow 2 set to ~400 slm.
 - * Electronics testing completed, compressor powered off.

HDice

- NMR program asynchronous mode debugged.
 - * Asynchronous mode would crash with a memory error after ~ 7 cycles.
 - The memory leak was caused by the field display array not being cleared between cycles while running in asynchronous mode.
- Initialization sequence on Fast Resonance Scanner program debugged.
 - Program halted with an error during the instrumentation communication check in the initialization sequence.
 - The model number for the Rack #1 Rohde & Schwarz signal generator is different from Rack 2 causing the instrumentation communication check to fail.
 - The 7060 relay I/O module check also failed the instrumentation communication check because a 7060D (D for display) was used in the RF box.
 - * Code was changed to accept both model types of signal generators and relay I/O modules.
- Measurements of cable lengths and inventory of connectors and adaptors taken for RF cables in Rack 1.

<u>SVT</u>

- Wire between the cold plate faraday cage ground and the L1C on S3 M15 repaired.
 - ★ Was damaged either when MVT was removed from SVT or SVT "drip pan" was removed.
- Hardware interlock system updated to give averaging and trip delay controls to individual sensors.
 - Program upgraded to LabVIEW 2017 and deployed to test station cRIO for debugging.
 - Configuration file utility subVI corrected to implement new arrays for individual sensor controls.
 - Because arrays for new controls were not added to configuration file, the cRIO was always reading the configuration file as having a fault.
 - Changing averaging and trip delay controls to arrays and creating a new configuration file resolved issue.
 - * Program update complete and running successfully on test station cRIO.
- All 12 HTSB2 cables fabricated.

LTCC

• Leak test setup for sectors 2 and 3 have been moved to the floor of Hall B for access to 160 subnet.

HTCC

- Flow increased to 18 Lpm.
 - Alarm settings in EPICs changed to 25 Lpm.

Gas System

- Assembly of the first MFC power chassis started.
 - * Machine work necessary to install dual power supplies and power supply redundancy module completed.



Weekly Report, 2018-06-20

<u>Antonioli, Mary Ann</u>

- Worked on formatting and editing 3-page table for Pablo's Note.
- Attended Hall C safety walk-through.

Bonneau, Peter

HDice

- Working with Amanda on the debugging of the asynchronous operating mode on the NMR program.
 - * Asynchronous mode would crash with a memory error after ~ 7 cycles.
 - * Synchronous mode successfully passed 2000 cycles.
 - The display processing of multiple-cycle field data is different between modes due to the greater density with synchronous operation.
 - The memory leak was caused by the field display array not being cleared between cycles while running in asynchronous mode.
 - The memory leak was fixed and an extended asynchronous test run of 2000 cycle sweeps was started.
- Debugged initialization sequence on Fast Resonance Scanner program.
 - Program halts with an error during the instrumentation communication check in the initialization sequence.
 - * The model number for the Rack #1 Rohde & Schwarz signal generator is slightly different from Rack 2 causing the instrumentation communication check to fail.
 - The 7060 relay I/O module check also failed the instrumentation communication check because a 7060D (D for display) was used in the RF box.
 - Code was changed to accept both model types of signal generators and relay I/O modules.

<u>SVT</u>

• Setup SVTCRIO2 cRio for testing the Hardware Interlock System software upgrade code by Mary Ann and Tyler.

Hall C

- Held daily status and planning meeting on HMS and SHMS PLC control systems.
 - Work on how the HMS & SHMS field regulation routine and interface to NMR and the power supplies is progressing.
 - * HMI control and monitoring screens were reviewed.
 - ***** UPS interface has been received.
 - * DSG is waiting on information from Hall C on spectrometer vacuum controls and shutter wiring diagram.

Campero, Pablo

Hall C

- Worked on HMS and SHMS Dipole field regulation PLC routine.
 - * Analyzed existent SHMS Dipole PLC program to understand current logic and configurations used in the system.



Detector Support Group Weekly Report, 2018-06-20

- Revised specs for Flex I/O adapters and Profibus modules used to transfer data from serial RS232 to ControlNet in SHMS PLC systems.
- Check commands sent to regulation module RG2024 which is use to send and receive data from the NMR and PSU to the PLC.
 - PLC Dipole code sends separates commands to the RG2024 module to perform the field regulation.
- * Determined that implementation of new routine to perform the Dipole field regulation and NMR PT2026 unit will request modifications in several existent PLC programs and HMI screens.
- Collaborated with Brian to set up SBC card.
 - * Connected keyboard, mouse, and display to the SBC card to run Linux OS.
 - * Assigned IP address (129.57.195.33) to be in the Hall C- DEV subnet.
 - * Pinged PT2026 NMR unit from the SBC card to test communications.
- Installed Factory Talk View Studio v10 on DSGPLC1 and dsg-hallc-2 PCs to run HMI (.SED) files used for SHM and HMS.
 - Debugging issues related with "unnamed displays" as consequence of incorrect software version used to open HMI files.
 - * Run SHMS and HMS projects in "grace period", since there is no available license to run more than 25 displays in FactoryTalk View SE.
 - * Started to look into Dipole MPS, Interlocks and NMR screens.
- Met with Joe to discuss about shutter controls and monitoring.
- Generated Hall C weekly report with the status of task performed by DSG.
- Collaborated with Tyler to turn on the **<u>RICH</u>** air compressor to allow test in the electronics.
- Provided layout and measurements for the length for six coaxial cables that will be used in the <u>HDice NMR</u> instrumentation at the rack #1.
- Researched about NI 9205 ADC module to be tested in the **<u>cRIO Test Station</u>**
 - * Analyzed specifications for absolute accuracy at different input ranges.
 - * Proposed wiring to connect grounding differential voltage signals to the module.
 - Differential measurement configuration allows more accurate measurements and less noise in the input signals.
- Revised and edited Solenoid Cooldown PLC Programs <u>DSG note</u>
 - * Generated table with detailed explanation for two DBX PLC programs that are used to calculate Solenoid cooldown parameters and enable the cooldown interlock s.
- Installed Studio v31on DSGPLC1 PC.

<u>Eng, Brian</u>

<u>SVŤ</u>

- Repaired L1C ground that was damaged either when MVT was removed from SVT or SVT "drip pan" was removed.
 - https://logbooks.jlab.org/entry/3577938



Weekly Report, 2018-06-20

Gas System

- LTCC setup in ESB was moved to Hall B.
 - * Needed to move from 86 to 160 subnet.
 - Marc and I got the hardware ready for leak testing, need to double check code for IPs.

Hall C

- Received SBC, installed Debian (official version from vendor) on SD flash while waiting for eMMC storage to arrive.
 - ★ Found that NI VISA won't install (not supported on that version of Linux or architecture, x86_64 only).
 - * Bypassed bad VXI implementation on NMR unit with Python VXI11 driver, can now communicate with instrument from SBC.

<u>Hall D</u>

- Slow controls meeting. Scot is changing DC gas setup, after his work is complete will upgrade NBX firmware.
- PXI upgrade on hold while waiting for CC to deploy new PTP server.

Hoebel, Amanda

HDIce

- Debugged NMR program.
 - * Program would hang-up during non-sync mode.
 - Problem found to be not clearing graphs during non-sync mode at the beginning of a sweep.
- Measured RF cables in Rack 1 for Rack 2 fabrication.

Hall C

- Took Hall C walkthrough.
- Spoke with Joe Beufait on shutter wiring diagram, with Pablo, Tyler, and Brian.
 - * Discussed possible way to allow shutter-in-place detection.
 - Would have to hook up voltage loop.
 - Probably not enough pins in the shutter wire.
- Found table of commands in Danfysik 8000 PS manual.

Jacobs, George

• Ordered additional hardware for RICH N2 ppm H2O sensor installation.

Leffel, Mindy

HDICE

- Controls rack cables.
 - Took inventory of connectors and adaptors, need one SMA connector, will need more of each if more cables are needed.
 - ★ Started fabricating cables.



Weekly Report, 2018-06-20

<u>SVT</u>

- HTSB2 cables complete.
 - * Tested for continuity.
 - * Affixed Kapton tape to back of boards for isolation.
 - * Attached two layers of heat shrink for strain relief.
- Hall C safety training.

Lemon, Tyler

- Powered on <u>**RICH</u>** air-cooling compressor for electronics debugging with Pablo.</u>
 - * Airflow 1 set to ~500 slm, airflow 2 set to ~400 slm.
- Tested and debugged update to <u>SVT</u> hardware interlock system to give averaging and trip delay controls to individual sensors.
 - * Update made by Mary Ann in LabVIEW 2016.
 - Updated program to LabVIEW 2017 and deployed it to test station cRIO for debugging.
 - * Corrected configuration file utility subVI to implement new arrays for individual sensor controls.
 - Because arrays for new controls were not added to configuration file, the cRIO was always reading the configuration file as having a fault.
 - Changing averaging and trip delay controls to arrays and creating a new configuration file resolved issue.
 - * Program update complete and running successfully on test station cRIO.

Hall C

- Met with Joe Beaufait to discuss SHMS shutter.
 - * SHMS shutter uses two separate voltage signals: one causes shutter to close and one to cause shutter to open.
 - Shutter is only either fully open, fully closed, or uninstalled.
 - * SHMS shutter has LED indicators in hall to show whether it is open or closed.
 - * SHMS shutter remote monitoring/controls via PLC only allow users to open shutter or see if shutter is open.
- Implemented borrowed Hall C 1756-IB16D diagnostic digital input module in DSG's PLC test station for development of UPS monitoring.
 - * Relay card for small UPS will send a 24V signal to HMS I/O chassis digital input.
 - * There are several spare diagnostic digital inputs for relay card output.
 - Also investigating how to use diagnostic input to sense a broken wire to potentially use relay as a short between input terminals without 24 V supply.

McMullen, Marc

LTCC

• Set up mobile pressure/flow monitor and controls in hall b. Sectors 2 and 3 have been moved to the floor of hall b.



Weekly Report, 2018-06-20

Gas System

• Started assembly of the first MFC power chassis. Completed machine work necessary to install dual power supplies and power supply redundancy module.

HTCC

• Increased flow to detector to 18Lpm and changed alarm settings in EPICs to 25Lpm.