

# NPS Mounting procedure

## 01/26/2021

**Unité mixte de recherche**  
**CNRS-IN2P3**  
**Université Paris-Sud 11**

91406 Orsay cedex  
Tél. : +33 1 69 15 73 40  
Fax : +33 1 69 15 64 70  
<http://ipnweb.in2p3.fr>

# Task 1 :Open the wood box



Open first the rear plate noted on the wood box



Then the other wood plates

## Task 2 :Open the wood box




2: Remove all the black plates





Task 3 :Remove the 30 PCB



Remove the protection of anode cables




Don't remove the individual bags for cables in order to avoid to loose the connectors nuts



Remove The Plastic parts which maintain blocked the PCB ( Top x 2 + bottom x1)



Task 4 :Remove the 30 PCB



4:Remove all the PCB ( take care the anode wires) The HV cables are not connected

# Task 5 :Remove the bottom wood part



Remove the metal plate which is screwed on the bottom wood support (2 screws)



Backward corner

Remove the screws which maintain the Aluminum frame on the bottom wood support (6 screws)




**Task 6: Lift the box and pull down on the Jlab support frame**



Use the 4 lifting rings


Fixing the box on the frame ( 6 screws)



Jlab frame ? **52 cm**




## Task 7: Removing all the 1080 PMt supports



7 :Unscrew each fixation screw ( 1/PMT support) and pull the PMT support . Take care the fragile Mu metal tubes

# Preparation before mounting :Task 8



8 : Remove the 2 scintillators

## Preparation before mounting :Task 9



4 connectors

A close-up photograph of a metal plate with four copper connectors. A red arrow points from the text '4 connectors' to the connectors. The plate has a grid of circular holes. A fan is visible in the background.



4 tubes


A photograph showing four copper tubes connected to a metal plate. A red arrow points from the text '4 tubes' to the tubes. The plate has a grid of circular holes. A fan is visible in the background.

9 : disconnect all the copper tubes connected on the Reference and the support PMt aluminum plates




Preparation before mounting :Task 10

3 Top tubes




3 bottom tubes



10 : disconnect the 6 copper tubes connected on the 4 cooling plates


Preparation before mounting: Tasks 11 and 12

Caution: 2 mm spacer between false shielding plate and vertical frame




11 : remove the 2 reinforcement arms

False shielding



12: remove the plastic plates (false shielding)


## Preparation before mounting :Task 13



13 : remove the front reinforcement aluminum plate




Preparation before mounting :Task 14



Need a tool to help the dismounting



14 : remove Top Aluminum plate with its connectors and cables

## Preparation before mounting :Task 15



15: remove the 2 threaded rods and the fixing base plate screws T nuts ( 4 @ the front and 3 @ the back)



Preparation before mounting :Task 16



16 : remove the calorimeter support (without the support frame)



Preparation before mounting :Tasks 17 , 18





17 : remove the 4 Copper cooling plates

18 : remove the front PE plate with its T° sensors




Preparation before mounting :Task 19




19 : remove the front frame


Preparation before mounting :Task 20



Iron bottom  
shielding plate





**!Before: Test the complete mounting and check dimensions of Shielding (Jlab)**



20 : remove the 4 screws under the base plate

Replace the false shielding with the iron bottom shielding plate

# Mounting :Task 21




21 : Mounting of the 4 screws under the base plate and adjustment of the position both base plate and bottom iron shielding plate



**Mounting :Task 22**



Check regularly during the stacking (each row) of crystal to keep the good gap in order to permit the mounting of the top horizontal frame @ the end!!! (given by the tool)



2 temporary tools (Top position) to maintain the good position of the 2 vertical Aluminum frame


The Top frame is not monted to permit the free movement of vertical carbones, help for sliding the crystals and put hands through the vertical carbon plates

6 threaded rods @ bottom  
 3 only on the sides to keep a good access with hands during crystals stacking




**22 : Mounting of the front frame**

# Mounting :Task 23



! Difficult access for tight in the box



23: Mounting of the tubes bottom right (tight them and check no leak)



Put the 2 threaded rods and the fixing base plate screws T nuts ( 4 @ the front and 3 @ the back)

Take care the bottom tubes !

Side base plate aligned on extremity frame




5 mm / front side


24 : Mounting of Calorimeter support in the box



Mounting :Task 25





Mounting 1st layer  
bottom insulating foam  
(1 part)







Mounting bottom left  
cooling support

Mounting 2nd layer  
bottom insulating foam  
(7 parts)



25 : Mounting of the bottom insulating foam

**Mounting :Task 26**



**! Take care T° sensor wires**

**! Mu metal fragile**

Put tape 12 mm Top and Bottom frames to maintain the plates



Slide the vertical mu metal plates (caution don't bend them ,very fragile)

**26 : Mounting of the vertical Mu metal plates**

Put gloves to manipulate the mu metal


**Mounting :Task 27**

**! Take care Mu metal edge**



Slide the bottom plate between aluminum spacers and Mu metal

Contact with front frame in order to block carbon plates





**27 : Mounting of the bottom cooling plate**

Mounting support parts screwed on the bottom iron plate (check the contact both front aluminum frame and side of copper plate : maintain of the vertical carbon plate)




Mounting :Task 28

! Take care T° sensor wires





28 : Slide the bottom horizontal 1,5 mm mu metal

Mounting :Task 29




29 : Re-connect the bottom right tubes

Mounting :Task 30





Put the front alu plate



30 : Slide the vertical carbon plates




**Mounting :Task 31**




Gap 0,25 mm between the aluminum frame and the 1st raw carbon



Necessity to put 0,25mm adjustment shims




Insert 30 adjustment shims




contact

**31 : Slide the 1st horizontal carbon plate and 36 adjustment shims**



The frame is  
ready to insert  
the crystals



32 : preliminary mounting of the 2 reinforcement 2 arms



33 : Wrapping Crystal : see note about wrapping



# Mounting :Task 34





Can be glued in order to be fixed if PMt removed

Contact with Aluminum part

Insert all the raw


**34: inserting the stop plastic part which maintain axially the crystal**




35: insert the 1st crystal with its wrapping

For a better access  
you can bend the  
vertical carbon plate


**Mounting :Task 36**



Insert Brass tool for adjustment in the upper holes raw of the support PMT plate




Measurement of the gap



Gap


Check the good gap = 1,05 mm with a tool (slide the tool between the Top face of crystal and cylinder)




**36 : Adjust the backward height of the crystal**



Mounting :Task 37



Insert carbon tool and slide it




Check gap = 0 with a tool





After measurement adjust the tape thickness and check

37 : Adjust the Front height of the crystal



38 : insert the first raw of crystals with this method



Then put tape in order to block the horizontal carbone

4 parts : 2 @ the front and 2 @ the other side of the frame



39 : slide the carbon horizontal plate



# Mounting :Task 40

Caution !!! This plate is very fragile (soft) , don't bend it because it would loose its shielding properties




Use a rigid plate below to move it



Check the gap : you never must not superpose the mumetal on the Tedlar


40 : insert the first 0,5 mm thick horizontal Mu-metal

Insert the 2 pins in the holes




Rotate the plastic part

41 : insert the front plastic parts with reflective sheet




42 : insert the Layer of front plastic parts with reflective sheet



1 row out of two the horizontal carbon plate is inserted in front of or behind the front Aluminum frame

43 : Repeat the tasks 34 to 42 for each row






Until the row 29  
we keep the  
tool which  
replace the  
horizontal Top  
Aluminum  
frame which let  
free the vertical  
carbon plates

44 : stacking until the raw 29

## Mounting :Task 45




Mounting of the top  
Aluminum frame

Remove the 2 rods in order  
to remove the tools , then  
put it on with the spacer

Remove the tool  
**only after the  
mounting of the  
top frame and the  
threaded rods !!!**

45 : mounting of the Top Aluminum frame


Mounting :Task 46




46 : Stacking the 6 last raws

Mounting :Task 47

Add temporary 3 threaded rods with spacers at the top



!!! Remove the side rods after add top rods




Then ,Remove temporary all the threaded rods with spacers at the right side to permit to insert the right side coper plate

47 : remove right side threaded rods for copper plate mounting





Mounting :Task 48


1: insert aluminum spacer 1mm on the bottom plate



2: insert vertical copper plate




Put screw





48 : mounting of the vertical right side copper plate

Mounting :Task 49




49 : mounting of the right side rods with spacers

Mounting :Task 50



Put 2 screws


Put all  
Rods with  
spacer on  
left side




50 : mounting of the left side copper plate

1 : remove all the  
top threaded rods

2 : put the spacers  
(adjustment in  
order to be above  
the mu metal plate)




3 : insert the top  
copper plate)




51 : mounting of the corners to fix the Top copper plate






Put the brackets  
and screws




Finally put all the tops threaded  
rods with their spacers

52: mounting of the Top side copper plate



Mounting :Task 53



53 : mounting of foam around the copper plates




Before ,remove the 2 reinforcement arms



54: mounting of vertical Shielding plates



Mounting :Task 55



55 : mounting of Top Shielding plate



# Mounting :Task 56




**!!! Spacer 2 mm  
between Aluminum  
frame and vertical  
shielding plates**


**56 : mounting of the arms and spacers 2mm**

# Connecting cooling and test :Task 57

Support PMt plate



detail





Reference plate

See cooling system note

57 : Connection of all the copper tubes and tightness test

# Mounting :Task 58



T° sensors





58 : mounting of the PE front plate and its sensors

Mounting :Task 59

29 screws M4 x 20




10 large  
washers and  
Nuts M8



The other threaded rods are temporary without large washers and nuts in order to permit the mounting of the Aluminum reinforcement plate for moving the calorimeter


59 : mounting of the PE front plate and its sensors






60 : mounting of the front foam

Mounting :Task 61



61 : mounting of the Top plate with its connectors and cables

Mounting :Task 62




62 : sensors cabling



63 : assembling 1080 PMt and their base







1080 + 20 = 1100 spares sheets 50 $\mu$  91mmx75 mm

64 : assembling 1080 Kapton sheet 50 $\mu$  and tape for HV protection

Mounting :Task 65



Slide the PMt until the plastic washer of the support



65 : assembling of 1080 Pmt +base + kapton into the PMt support

# Mounting :Task 66



1 : insert the fiber first in the PCB plastic ferule on a table

Put the sheath around the fiber to press the fiber with the aluminum bars


Put all the 36 fibers and block them with screws

+ Connect Anode and HV cables in front of PCB

Then each other extremity of fiber will be inserted in the PMt support ferule when PCB installed ( column)



66 : mounting of fibers and front cables (anode + HV) on PCB



67 : mounting of 1080 PMt assembly on the PMt support plate


Method : see next pages




- 1 : put optical grease on the front glass face  
Necessity to optimise the grease quantity



- 2 : insert the PMt with its support throw the Aluminum plate hole




- 3 : Tighten the screw with a screw driver



68 : mounting of 1080 PMt assembly on the PMt support plate

4 : Make a rotation of the PMt by hand with the help of base in order to spread the grease between the crystal and the PMt


5 : use a nut driver in order to press the 2 nuts on the plastic washer and press the springs



**VERY IMPORTANT !!!**

**When contact (use fingers to screw) between nuts and washer, rotate  $\frac{1}{4}$  turn Maxi with nut driver ( not more in order to limit the force on the crystal and limit the force on the plastic front part , we need just a contact between PMt and crystal)**

6 : Then ,Put vernish on the threaded rods to avoid loose them





69 : mounting of 1080 PMt assembly on the PMt support plate

70 : mounting of the additionnal T) sensors @ the back (electronics)

71 : mounting of Gas connections





Mounting :Task 72



72 : mounting of the first left PCB

Connect HV connectors and  
put the Top aluminum bar

# Mounting :Task 73




Slide the fiber until the crystal throw the plastic washer, then Tighten the metal ferule to block it

Metal ferule

73 : connect the fiber and front cables on PMt support

Mounting :Task 74



74 : connect the LED flat cables to the LED PCB



Mounting :Task 75



Put the cable on the support bars and connect them to the Lemo connectors

+ test LED

75 : connect the anode cables to the Top plate

Mounting :Task 76




76 : mounting of the others PCB

Repeat the steps 72 to 75 for each PCB



Mounting :Task 77



77 : Close the box