



# Detector Support Group

## Weekly Report, 2017-06-07

### Status

#### Solenoid

- Option to enter set point values for flow rates in vapor cooled leads A and B written and tested.
- Circuit diagram to calculate current in *Dump Resistor* verified.
- Formulas to relate resistance to estimate temperature analyzed.
- PLC code for Solenoid and Torus magnets verified.
  - ★ Found *EPICS\_Watchdog fail* is not an interlock for Torus or Solenoid.
- Updates on Solenoid PLC code made to solve issues with EPICS screens tested.

#### RICH

- User Interface LabVIEW program completed.
- Procedure reviewed to implement NI work-around solution for loss of communication with EPICS.
- Hardware Interlock System CSS screen updated to include EPICS control status indicator and indicator color changes.
- Electronics “dark box” testing will use SVT R4 cover.

#### FT

- System Monitoring and Expert Control Setting tabs on GUI for EPICS hardware monitoring system created.
- Installation, testing, and debug of interlock system performed.
- EPICS GUI interface for client CLAS12 PV signal names programmed.
- Two humidity sensor cables and various other cables fabricated.
- Two cables incorrectly wired from FT group repaired.
- Hardware interlock system ready for FT group to test.

#### SVT

- Region 4 removed.
- Data and pulser cables rearranged.
- MVT integrated with SVT.

#### Gas System

- Purge lines for eCal installed for 4 sectors.
  - ★ Crane operator required for remaining 2 sectors.

#### Hall D

- PXI communication errors debugged.
  - ★ Started working again after multiple reboots.
- Newly repaired and calibrated solenoid GHe mass flow controllers installed and tested on upstream and downstream VCLs.
- Temperature in BCAL chillers increased to 18 °C on 06/06/17.



## Detector Support Group

Weekly Report, 2017-06-07

### Antonioli, Mary Ann

#### FT

- Using CS Studio, created cRIO System Monitoring and Expert Control Setting tabs on GUI for EPICS hardware monitoring system.
  - \* Created EPICS names for signals read on tab.
  - \* Assigned signal names to CS Studio objects.
- Began AutoCAD wiring diagram of cRIO chassis.
  - \* Drew chassis and components.
  - \* Most of power system, temperature, and humidity completed.

### Arslan, Sahin

Absent

### Bonneau, Peter

- Worked with Amanda, Tyler, and Pablo on EPICS interface for **RICH** real-time program, reviewing procedure to implement NI work-around solution for loss of communication with EPICS.

#### Forward Tagger Interlock System.

- Worked with Amanda on installation, testing, and debug of interlock system in EEL.
  - \* Programmed calorimeter chiller to accept input pump disable signal from interlock system. Programmed chiller output analog interface to provide pump pressure and status to NI ADC.
  - \* Tested interlock enable and threshold controls for calorimeter internal temperature and humidity sensors and N<sub>2</sub> MKS mass flow meter.
  - \* Programmed Mpod LV controller to accept individual channel enables for calorimeter and hodoscope.
  - \* Verified interlock system control of HV and LV supplies.
  - \* Tested HV to LV trip delay controls for calorimeter and hodoscope.
  - \* Tested threshold and enable controls for hodoscope temperature using temporary sensors. DSG has requested hodoscope temperature cable length from FT Group.
- Programmed CS-Studio EPICS GUI interface for client CLAS12 PV signal names.
- Developed and tested EPICS client interface and test program for FT Interlock System.
- Installed and tested work-around solution for loss of communication between EPICS and NI cRIO processor. Tested on both cRIO server and client modes.
- Worked with Mary Ann on programming of CSS signal monitoring tabs and wiring diagram for cRIO.
- Worked with Mindy on required cables.
- Held daily meeting on Hall D status and EPICS controls monitoring.
  - \* Newly repaired and calibrated solenoid GHe mass flow controllers were installed and tested on both upstream and downstream VCLs. Controllers were set to final configuration of 31.15 SLPM.



## Detector Support Group

Weekly Report, 2017-06-07

### Campero, Pablo

#### Solenoid

- Wrote and tested PLC code to add option to enter set point values for flow rates in vapor cooled leads A and B.
- Discussed with Tyler and Probir calculations of new estimated temperatures that will be implemented for each coil.
  - \* Verified circuit diagram to calculate current in *Dump Resistor*.
  - \* Defined that voltage across *Dump Resistor* will be taken as voltage over whole magnet, which is voltage tap measurement for VT-20\_DAQ.
  - \* Analyzed formulas to relate resistance to estimated temperature.
  - \* Defined five tag names that will be used to monitor these values in PLC and EPICS.
- Verified PLC code for Solenoid and Torus magnets and found that *EPICS\_Watchdog fail* is not an interlock for Torus or Solenoid.
  - \* PLC logic for *EPICS\_Watchdog fail* is disabled at this time.
- Tested updates on Solenoid PLC code that were made to solve issues with EPICS screens.
  - \* Load Cell, EM-Forces, Temperature Details, Hall Sensors and LHe-SST screens were fixed; mismatch on tag names and data type were solved.
  - \* Tested correct readback values on each screen.

#### RICH

- Completed User Interface LabVIEW program.
  - \* Wrote LabVIEW code to complete User Interface, Hardware Interlock Event Handling, and Control Configuration loops.
  - \* Completed EPICS Interface to UI loop. Configured indicators to display updates on thresholds that will be entered from EPICS side to User Interface VI.
  - \* Debugged front panel view by organizing indicators and buttons in correct tabs and tables.
- Monitored and analyzed Logbook entries and EPICs screens daily.
  - \* On 6/6 noticed that temperature in the BCAL chillers increased to 18 °C.

### Eng, Brian

#### SVT

- Removed R4, including all electronics.
- Rearranged data and pulser cables: <https://logbooks.jlab.org/entry/3474885>

#### MVT

- Integrated MVT with SVT.
- Swapped Ar bottle.
- Met with Bob and Stephan concerning gas mixing system. Equipment was removed to save costs. Bob is aware this will be less automated and therefore require more manual oversight.



## Detector Support Group

### Weekly Report, 2017-06-07

#### Magnets

- Got a 325 K error (according to cRIO), but no corresponding spike in EPICS data. Will continue running either until we get a clear error and recovery or Hall B is ready to power on Torus (so we can deploy the real-time executable).
- Debugging **PXI** downtime with Tyler: <https://logbooks.jlab.org/entry/3474459>

#### Hoebel, Amanda

- De-cabled **SVT** electronics rack with Brian.
- Analyzed **LTCC** leakage rates.
  - ★ Created histograms of fill times in Python.
  - ★ Calculated average leakage in L/day for each sector.
  - ★ Leakage rates based on flow similar to Brian's measurements.

LTCC Leak (in L/day)

	S1	S2	S3	S4	S5	S6	Total
Amanda	102.69	61.15	134.47	84.08	57.34	149.11	20609.54 L
Brian	112.54	51.59	125.8	54.01	43.52	139.89	18456.90 L

Leakage based on flow rates for 6 LTCC sectors from Python program compared to Brian's measurements, from 2017-04-25 to 2017-05-30, omitting 2017-05-10 and 2017-05-11.

#### FT

- Tested interlocks with Peter.
  - ★ Confirmed functionality of sensor enables.
  - ★ Verified interlock errors latched by system and checked reset function.
  - ★ Checked trip threshold values for calorimeter temperature, humidity sensors, and gas flow.
  - ★ Tested HV-LV trip delay.
  - ★ Verified system turn-off of chiller pump.
- Added rules to EPICS interlock PV indicators.
  - ★ Indicators are red when status trips.

#### Gas System

- Attended eCAL safety walkthrough.
- Ran gas lines for eCAL with Tyler, Mindy, and George.
- Monitored EPICS and logbook.
  - ★ Two mass flow controllers repaired and re-installed for solenoid on 05/31/17.

#### Jacobs, George

No report received.



## Detector Support Group

Weekly Report, 2017-06-07

### Leffel, Mindy

- Worked in hall B with Amanda, Tyler, and George running eCal gas system purge lines.

#### FT

- Contributed to chassis installation, setup, and testing.
  - \* Fabricated two humidity sensor cables and various other cables.
  - \* Repaired two cables incorrectly wired by FT.

#### HTCC

- Discussed repair of signal cable with Youri.
  - \* Started repair in hall B, could not finish, as was given incorrect connectors.
  - \* Located correct connectors and returned wrong ones to stockroom.

### Lemon, Tyler

- Attended Solenoid Cooldown ERR dry run.
- Ran three ECAL gas lines with Mindy, Amanda, and George.
- Updated RICH Hardware Interlock System CSS screen.
  - \* Added indicator to show EPICS control status.
  - \* Added rules to blink sensor value indicators yellow and red if sensor is out of bounds.
  - \* Added rules to change sensor status color to yellow and display “disabled” if that sensor is disabled.
- Wrote program in Python to analyze LTCC gas leak data.
  - \* Program calculates gas leak using pressure drop, as follows:
    - Reads data from Excel sheet.
    - Finds “pressure decay periods” (periods less than 150 minutes with no flow).
    - Calculates leak rate using absolute pressure drop over pressure decay period.
    - Fits each pressure decay period’s data to an exponential decay equation.
    - Calculates leak rate using pressure drop as given by fit results.
    - Generates histograms for all decay periods’ leak rates, pressure drops, mean ambient pressure, and time interval.
  - \* Numerical results do not match what Brian has measured, but ranking from best to worst for results obtained using exponential decay fit match (Python results below).



## Detector Support Group

### Weekly Report, 2017-06-07

### Leak Rate from Pressure Decay

From 2017-04-25 17:04:16 to 2017-05-30 08:45:33\*

#### Calculation Results Ordered Lowest to Highest Average Leak Rate

Sector	Average Leak Rate [L/Day]	Standard Deviation [L/Day]	Total Flow [L]
5	42.01	6.22	1455.65
2	42.06	8.16	1457.58
6	45.65	10.32	1582.04
4	45.83	15.38	1588.01
1	50.53	11.49	1751.16
3	52.62	15.03	1823.36

#### Fit Results Ordered Lowest to Highest Average Leak Rate

Sector	Average Leak Rate [L/Day]	Standard Deviation [L/Day]	Total Flow [L]
5	39.54	7.60	1370.35
2	40.54	10.53	1404.85
4	42.96	9.14	1488.86
6	44.25	11.33	1533.33
1	47.64	12.00	1650.73
3	50.23	14.86	1740.52

\*2017-05-09 11:00:00 to 2017-05-11 19:00:00 skipped due to incorrect data from deadband experimentation.

- Debugged **Solenoid** PXI communication errors with Brian.
  - ★ PXI was not sending data to EPICS and was not responding to pings.
  - ★ No errors initially on console, but error received when PXI power-cycled.
  - ★ Changed PXI to use static IP address.
  - ★ Updated PXI software and LabVIEW program to LabVIEW 2016.
  - ★ On later power-cycles, error remained or PXI self-rebooted into safe mode.
  - ★ Was not able to start LabVIEW project consistently.
    - Start-up app would not deploy, but was able to deploy VI manually.
    - Able to restart program after opening VI in debug session, then stopping and starting VI after it froze during initialization.

**McMullen, Marc**

Absent