



Detector Support Group

Weekly Report, 2018-05-02

Summary

HDice

- Debugging of error in NRM program regarding the end-of-scan field setting completed.
 - * For some scans, the program would not completely finish the field ramp-up at the end of a cycle.
 - * It was found that the program was issuing a ramp-hold command too early during the field ramp-up when the buffer limit was reached.
- Communication debugged for Mercury IPS power supply.
 - * Power supply unable to read SCPI commands sent via USB connection.
 - Updated Gadget Serial drivers.
 - TeraTerm downloaded and installed to test serial/USB port connections.
 - * After debugging, the connection could not be still established.

RICH

- EP cRIO's hardware interlocks program updated to give ability to enable trip delays with user-set time over threshold requirements for individual sensors.
 - * Previous version used global trip delay control settings for all sensors.
 - * Update successfully tested on development cRIO; will be deployed to EP cRIO over summer shutdown.
- Wiring schematic and code developed to allow remote software override for both cRIOs in the hardware interlock cRIO.
 - * Each cRIO will serve a remote relay override for the other cRIO in RICH's dual-cRIO interlock system.
 - * Successfully tested preliminary version for remote override on development cRIO.

SVT

- New humidity and temperature sensor boards arrived.

Gas System

- New design for MFC power distribution chassis completed.
 - * Chassis adds additional fusing and ability to take signal box offline without effecting MFCs.
 - * Request for quote to Par-metal enclosure sent.

Hall B Magnets

- Quartus 17.1 software installed on Linux, software used to program FPGA board.
- Development code for the LV chassis' FPGA board in progress.
 - * GitHub repository for FPGA created.
 - * FPGA-only mode builds fine on new development board.
 - * Having some issues getting "System on a Chip" (SoC) part deployed/running properly.
 - SoC will allow direct communication with the PLCs.

Detector Support Group

Weekly Report, 2018-05-02

LERE

- Both Harp power distribution boards populated.
- Populating one of six VME FSD fiber card boards for Machine Protection System started.



Harp power distribution board

cRIO Test Station

- Wiring between NI-9207 and NI-9265 modules completed.
 - * D-sub connector soldered and wired according NI technical specification.
 - * Problems found with current “bleeding” into other channels.
 - * LabVIEW code written to test set current and readout current (0-20mA) for NI-9265 and NI-9207 modules respectively.
- LabVIEW sub-VIs written to take current samples from channel 8 to 11 and calculate mean, accuracy, and standard deviation.
 - * Sub-VIs added to manual and automatic mode tests.
 - * Sub-VI programs tested and debugged.

VME Test Station

- Instrumentation for test station configured and tested.
 - * Serial communication problems between Keithley voltage source and PC solved.
 - Bad RS-232 cable changed; adaptor added to convert serial to USB connection.
 - * LabVIEW program written to set voltage output in the Keithley power source.

Hall C

- Meeting held with Steve Lassiter, Jack Segal, and Mike Fowler regarding Hall C magnets control systems.
 - * Hall C is requesting assistance with the magnet control systems for their High Momentum Spectrometer (HMS) and Super High Momentum Spectrometer (SHMS).
 - * Hall C will make a list of control system hardware and programming tasks with timeline completion dates where DSG can contribute.



Detector Support Group

Weekly Report, 2018-05-02

Antonioli, Mary Ann

cRIO test stand

- Completed wiring of 9207 D-sub connector for connection to 9265 module (current supply) for testing 9207 channels 8-11. Tested by Pablo.
 - * Problems found with current “bleeding” into other channels.
 - * Wired a second connector; tested; works.
- Wrote subVI to take current samples from one channel of 8-11 and calculate mean, accuracy, and standard deviation.
 - * Tested and debugged. Works.
 - * Added subVI to manual mode of User Interface and Main Real Time.
- Wrote subVI to take samples and calculate mean, accuracy, and standard deviation for all channels, 8-11.
 - * Added subVI to auto mode of User Interface and Main Real Time.
 - * Tested OK.
- Edited Pablo’s Hall B Magnets presentation.
- Took Standards of Conduct training.

Bonneau, Peter

HDice

- Completed debugging the error in NRM program regarding the end-of-scan field setting.
 - * For some scans, the program would not completely finish the field ramp-up at the end of a cycle.
 - * It was found that the program was issuing a ramp-hold command too early during the field ramp-up when the buffer limit was reached.
 - * Removing the ramp hold command at buffer limit allowed the first cycle in a run to always successfully complete the field ramp-up.
 - * However, removing the hold command during a run with multiple cycles, the program would start ramping too soon after the first cycle completion.
 - * A while loop was added at the field ramp-up sequence that waits and confirms that the power supply has fully completed the ramp up (by reading back the field) before issuing the ramp-hold command.
 - * Power supply now successfully completes the field ramp-up on single and multiple cycle runs.
 - * The error found was in the original NMR code written by Brookhaven.

Hall C

- Held meeting with Steve Lassiter, Jack Segal, and Mike Fowler regarding Hall C magnets control systems.
 - * Hall C is requesting assistance with the magnet control systems for their High Momentum Spectrometer (HMS) and Super High Momentum Spectrometer (SHMS).
 - * Hall C will make a list of control system hardware and programming tasks with timeline completion dates where DSG can contribute.



Detector Support Group

Weekly Report, 2018-05-02

- * DSG will evaluate the list and given our other commitments, see where and if we can accommodate their task requests.

- Held meetings on Hall B and D detector and magnet status.

Campero, Pablo

HDice

- With Amanda debugging IPS power supply communication issues.
 - * Re-installed latest version of the USB drivers.
 - * Swapped USB type B cable. Probe that cable was not the problem in the connection.
 - * Downloaded and installed TeraTerm program to send and receive commands by opening serial connection.
 - TeraTerm unable to open the serial port and send any commands.
 - Error to open serial terminal.
 - * Run LabVIEW drivers used to set and read basic function, but immediately time out errors were showed due to communication problems.
 - * Power supply unable to read SCPI commands sent via USB connection, still debugging.

cRIO Test Station

- Installed and tested hardware for “ADC -Current Test” to be performed in the NI-9207 ADC module.
 - * Connected external power supply (+12 V) to the NI9265 AO module.
 - * Installed and wired NI9265 AO module and NI9207 AI module based on NI specification, used current loop diagram.
- Wrote LabVIEW code to test set current vs readout current on NI9207 and NI9265 modules respectively.

VME Test Station

- Configure and tested instrumentation to be used as part of the VME Test Station.
 - * Solved RS-232 communication problems with the Keithley voltage source and PC
 - Changed serial cable
 - Added an adaptor to convert serial to USB connection.
 - * Wrote LabView program to set voltage output in the Keithley power source.
 - Wrote basic drivers read and set voltage output, set power source to local and remote control, and set up serial configurations.
 - Measured output voltage by using Fluke DMV connected at the Keithley voltage output to verify accuracy and precision
 - Run program for different negative and positive voltage values.
- Attended Hall C magnet meeting magnets control systems task in which DSG can help.

Eng, Brian

Hall B Magnets

- Installed Quartus 17.1 software on Linux.



Detector Support Group

Weekly Report, 2018-05-02

- Tested development code for the LV chassis' board.
 - * Created GitHub repository for FPGA.
 - <https://github.com/JeffersonLab/clas12-fpga-lv>.
 - * FPGA-only mode builds fine on new development board.
 - * Having some issues getting SoC part deployed/running properly.
- For the Hall B gas systems reviewed and approved new chassis for MFC power distribution that Marc designed.
 - * Chassis adds additional fusing and ability to take signal box offline without effecting MFCs.
- Upgraded one computer to Windows 10 to check compatibility with various software

Hoebel, Amanda

HDICE

- Attempted to establish communication with Mercury iPS.
 - * Could not get VISA drivers to work.
 - * Error on VISA read but not on VISA write.
 - * Updated Gadget Serial drivers.
 - * Troubleshooting:
 - Toggled between Legacy and SCPI commands in iPS.
 - Toggled between Remote and Local.
 - Tried Read and Write drivers.
 - Downloaded TeraTerm to test port connection.
 - * After debugging connection was not established.
- Made corrections to SVT health status report.
- Met with Hall C spectrometer support engineers to discuss work for Hall C.
- Took ODH 1 training.

Jacobs, George

LTCC

- Monitored daily LTCC S5 single sector test detector pressure and gas usage.
- Created LTCC Gas System Status 01 May 2018 power point presentation.


Leffel, Mindy

LERF

- Finished populating both Harp power distribution boards.
- Started populating one of six VME FSD fiber card boards for Machine Protection System.

Detector Support Group

Weekly Report, 2018-05-02



Harp power distribution board

Lemon, Tyler

RICH

- Updated EP cRIO's hardware interlocks program to give ability to enable trip delays with user-set time over threshold requirements for individual sensors.
 - ★ Previous version used global trip delay control settings for all sensors.
 - ★ Update successfully tested on development cRIO; will be deployed to EP cRIO over summer shutdown.
- Developed wiring schematic code to allow remote software override for both cRIOs in the hardware interlock cRIO.
 - ★ Each cRIO will serve a remote relay override for the other cRIO in RICH's dual-cRIO interlock system.
 - ★ Successfully tested preliminary version of code for remote override on development cRIO.
- Discussed potential causes of drops in measurements for N2 Volume Humidity 6 and 14 with Peter, Amanda, and Pablo.
 - ★ Signals for H6 and H14 suddenly dropped to below normal reading and then suddenly recovered.
 - ★ Potential causes include bad sensor, bad connection in wiring of sensors to cRIO, bad connection at d-sub connector at feedthrough from N2 Volume to atmosphere.
 - ★ During next open access period for Hall B, wiring of sensors to cRIO will be checked.
- Attended Hall C magnet meeting. In meeting, discussed:
 - ★ Overview of Hall C magnets system.
 - ★ Tasks Hall C is requesting DSG's help for.

McMullen, Marc

Hall B Gas System

- Completed gas system status presentation.
- Completed design for MFC power chassis and sent request for quote to Par-metal incorporated.
 - ★ Design work on the status LED board will begin this week.



Detector Support Group

Weekly Report, 2018-05-02




Diagram shows front view of the Gas Controls chassis used to power up MFCs in Hall B gas systems.

SVT

- New humidity and temperature sensor boards have arrived.
 - ★ Functionality tests will be performed after a few of them are populated.