



Detector Support Group

Weekly Report, 2018-09-20

Summary

Hall C

- Dipole field regulation PLC program completed.
 - ★ Conditions to start/stop regulation routines added, based on PSU read-back status.
 - ★ Filtering option for magnetic field readouts from PT2026 NMR unit completed.
 - ★ Comments added for each of the three routines:
 - Dipole_Field_Regulation: Main routine, used to control regulation logic needed to start/stop regulation, set operational limits and calculate field offsets.
 - Calculate_DI_Current: Routine calculates and sends to the MPS the required current which is based on magnetic field.
 - NMR_Read_B: Routine used to read the magnetic field and status from the PT2026 NMR unit.
 - ★ Program tested with Danfysik Python simulation program and HMI test screen.
- For 'End of life of Windows 7 and associated upgrade to Windows 10' task:
 - ★ Dsg-hallc-6 computer was rebuilt with windows 10.
 - ★ Changed graphics card.
 - ★ .NET Framework 3.5 installed; pre-requisite to install Rockwell Software.
 - ★ RSLogix5000 v.20.04.01 installed.
- Current Regulation PLC program for the HMS and SHMS quadrupoles tested using Danfysik Python simulation program.

Hall B Magnets


- Solenoid Fast Dumps Event table updated.
 - ★ Information added for the last three fast dump events that occurred at 2416 A on 08/27/2018, 08/30/2018 and 09/10/2018.

RICH

- Analyzed data from N2 flow loss on September 18, 2018 at 10:27AM.
 - ★ N2 flow lost in Hall B due to installation of isolation valve in the hall's nitrogen supply line.
 - New isolation valve allows flow to Forward Carriage or Space Frame to be stopped without affecting flow to the other.
 - N2 Flow lost for ~27 minutes.
 - ★ During period with no N2 flow, humidity increased ~0.3% RH in N2 volume.
 - ~30% overall increase in humidity.
 - ★ One hour after N2 flow was restored, humidity had decreased ~ 0.18% RH in N2 volume.
 - ~ 16% overall decrease in humidity.

Detector Support Group

Weekly Report, 2018-09-20



RICH N2 Volume humidity sensors during time with no N2 flow to about one hour after flow was restored.

HDIce

- Fast Resonance Scanner (FRS) program debugged.
 - ★ RF box failed to deliver RF while running the FRS.
 - ★ An incorrect communication port setting was discovered for the RS-485 interface for the RF box.
 - The incorrect port setting was most likely caused by the frequent Rack #1 computer crashes.

SVT

- Broken connector repaired for external chiller pump relay box cable.

Gas Control

- DC gas quality measurements at the exhaust evaluated.
 - ★ The R1-2 O₂ sensor read-back is off scale (> 1000ppm), while R3 ~400ppm.
 - ★ The moisture content for R1-2 is up to ~450ppm from a pre-storm value of ~350ppm.

CRIO Test Station

- Module 9205 differential nonlinearity test written, tested, and debugged.



Detector Support Group

Weekly Report, 2018-09-20

Antonioli, Mary Ann

- cRIO test station.
 - * Cleaned up project file, so had to change all Excel file paths; retested for 9205 module.
 - * Wrote 9205 module differential nonlinearity, with Krohn-Hite, test. Tested and debugged.
 - * Added above test into manual mode; currently debugging.
- Made final edits to and posted Note 2018-12.
- Formatted, edited, and posted Note 2018-13.
- Began reformatting Notes webpage.
- Attended Monthly Workers Safety Committee meeting.
 - * Heat stress presentation given by Jennifer Williams.
 - * FY18 safety and health objectives and targets presentation given by Mary Logue.

Bonneau, Peter

HDice

- Worked with Amanda, Tyler, and Pablo on the troubleshooting of the Fast Resonance Scanner (FRS) program.
 - * The FRS scan failed to produce correct spectrum.
 - * RF switch box failed to deliver RF during while running the FRS.
 - * An incorrect communication port setting was discovered for the National Instruments USB to RS-485 interface for the RF box.
 - * The incorrect port setting was most likely caused by the frequent Rack #1 computer crashes.
 - * Advised the HDice group to submit a CCPR for repair of their computer.
- HDice requested DSG to configure the computer in newly completed Rack #1 the same as the computer in Rack #2.
 - * DSG cannot reconfigure NMR Rack #1.
 - * Rack #2 disk was built from an HDice (non-CUE) Windows XP computer that was upgraded in 2015 to Windows 7.
 - * Computer center configured the Rack #1 computer in 2018.
 - * Any change to the configuration or repair of the Rack #1 computer must be done by the computer center.
 - * DSG has initiated a property transfer (and therefore administrator rights) for both NRM computers to the HDice group.
 - * The NMR computers must be upgraded by the computer center to Windows 10 in the coming year.
- Developing documentation on the use of the CAENels CT-box and DCCT head in the HDice NMR system.

DSG

- Investigation into the deletion of the link on the Hall D web page to the DSG webpage.
 - * Contacted David Chopard in Jlab Public Affairs regarding the link deletion.



Detector Support Group

Weekly Report, 2018-09-20

- * With the new the Drupal web development platform, webpage owners can edit their own pages including web links.
- * Jlab Public Affairs can also change webpages in response to requests from webpage owners.
- * David Chopard will return the DSG link to the webpage.
- * A class for the Drupal web development platform has been scheduled for 9/27 and 9/28.

Campero, Pablo

Hall C

- Dipole field regulation PLC program completed
 - * Added conditions to start/stop regulation routines based on PSU read-back status.
 - * Completed filtering option for magnetic field readouts from PT2026 NMR unit.
 - * Added comments for each of the tree routines wrote:
 - Dipole_Filed_Regualtion: Main routine, used to control regulation logic needed to start/stop regulation, set operational limits and calculates field offsets.
 - Calculate_DI_Current: Routine used to calculates the current based on magnetic field, which is then sending to the MPS.
 - NMR_Read_B: Routien used to read the magnetic field and status front the PT2026 NMT unit.
 - * Tested program by using MPS Danfysik Python simulation program and HMI test screen.
- With regards to task: End of life for Windows 7 upgrade to windows 10
 - * Dsg-hallc-6 computer was rebuilt with windows 10.
 - * Fixed hardware issues; changed graphics card
 - * Installed .NET Framework 3.5 as a pre-requisite to install Rockwell Software.
 - * Installed RSLogix5000 v.20.04.01
- Collaborated with Amanda to test Current Regulation PLC program for the HMS and SHMS quadrupoles.
- Updated Hall C PLC tasks table and compiled Hall C weekly report.

Hall B Magents

- Updated *Solenoid Fast Dumps Event* table
 - * Added information for the last three fast dump events occurred at 2416 A on:
 - 08/27/2018, 08/30/2018 and 09/10/2018
 - * Analyzed potential causes for the trips.
 - * Summarized the actions and task performed after each fast dump.

HDice

- Collaborated with Amanda and Tyler to debug Fast Resonance Scan FRS program running in NMR rack #2 (upgraded rack).
 - * Program unable to set correct output in the Attenuator RF box.
 - * Found communication issues between NI 485-Serial/USB adapter and PC.
 - Re-terminated and installed Ethernet cable to ensure correct connections.
 - Verified led status in NI485-Serial/USB adapter.
 - Check serial port assignment in the PC, rebooted it several times
 - * Solved communication issues by changing properties for the serial communication in NI MAX
 - Changed NI485-Serial/USB adapter option from 4 wires to 2 wires.



Detector Support Group

Weekly Report, 2018-09-20

- * Ran FRS LabVIEW program to test proper outputs in of the Attenuation box.

Eng. Brian

Hall B Magnets

- More testing of QD units.
 - * <https://logbooks.jlab.org/entry/3594064>
 - * <https://logbooks.jlab.org/entry/3594071>
- Solenoid Fast dumped again.
 - * <https://logbooks.jlab.org/entry/3594105>
- Tested QDs again.
 - * Found that the calibrators uses to set the threshold were in HEX instead of DEC mode.
 - * Threshold also raised from 100 to 200 mV for VCLs.
 - <https://logbooks.jlab.org/entry/3594137>
- Continued testing DAQmx as an alternative to using FPGA code for reading cRIO modules at full speed, so far testing has shown it can run at the same speeds.
 - * Still investigating other features being used by the FPGA (filtering, etc).

Hall C

- Configured EN2T modules for HMS primary and SHMS remote I/O modules, also CN2 modules for HMS.
 - * Needed CC to reconfigure hostnames for HMS ethernet modules since wanted to use the existing IPs.
 - * The new redundancy module RM2 uses a different optical cable than the previous model so the upgrade has been postponed until the next shutdown.

Hall D

- Still troubleshooting PXI timestamps with NI, another round of sending information and calling them, but so far no solution found.

Hoebel, Amanda

HDice

- Debugged NMR Rack #1 with Tyler and Pablo.
 - * FRS program was not working properly.
 - * Problem found to be incorrect setting in computer for RS485.
- Debugged NMR Rack #1 a second time.
 - * FRS program was not working properly again.
 - * Problem was found to be the RF generator unit stopped working.
 - Status light was blinking and gave error code “level not satisfied”.

Hall C

- Made current loop regulation routine for Q1 of HMS, with Hall C’s suggestions.

DSG

- Monitored EPICS and logbooks for Halls B, C, and D.



Detector Support Group

Weekly Report, 2018-09-20

- Put together the weekly report.

Jacobs, George

No report

Leffel, Mindy

HDICE

- Worked with Amanda, Pablo, and Tyler to replace RF box.

Gas System

- Continued fabricating MFC power chassis.
 - * Wired fuse holders and D-sub connectors.
 - * Installed redundancy modules and 24V DC supplies.

SVT

- Pump relay interlock CPC connector replacement.
 - * Attended meeting to discuss procedure and materials.
 - * Gathered materials with Marc.
 - * Worked in hall with Tyler replacing connector.

Lemon, Tyler

Hall C

- Completed note on UPS monitoring task.

RICH

- Analyzed data from N2 flow loss on September 18, 2018 at 10:27AM.
 - * N2 flow lost in Hall B temporarily for installation of isolation valve into the hall's nitrogen supply line.
 - New isolation valve allows flow to Forward Carriage or Space Frame to be stopped without affecting flow to the other.
 - N2 Flow lost for ~27 minutes.
 - * During period with no N2 flow, humidity increased ~0.3% RH in N2 volume.
 - ~30% overall increase in humidity.
 - * One hour after N2 flow was restored, humidity had decreased ~ 0.18% RH in N2 volume.
 - ~ 16% overall decrease in humidity.

Detector Support Group

Weekly Report, 2018-09-20



RICH N2 Volume humidity sensors during time with no N2 flow to about one hour after flow was restored.

HDice

- Debugged RF Box operations with Pablo and Amanda.
 - ★ RS-485 communication was not working for new rack in HDice lab.
 - ★ With Mindy, swapped RF box with spare, thinking that RF Box previously installed had issue.
 - Swapping RF Boxes had no effect on communication errors.
 - ★ Found that RS-485-to-USB adapter needed to be configured to 2-wire communication mode.
 - ★ Once settings of adapter corrected, communication errors stopped and all programs worked correctly.

SVT

- Repaired broken connector on cable for SVT external chiller pump relay box with Mindy.
 - ★ Verified correct operation of relay box using its LED indicators and the SVT hardware interlock system's LabVIEW User Interface.

McMullen, Marc

Gas Controls

- Continued work on Gas Controls daily report upgrade.
 - ★ Started modifying data-logger to change files at a specific time instead of at midnight.
 - This would allow the report to run until the open of the work day, while still changing at 24 hours.
 - ★ Additionally, the new modifications should allow the report to append to the file if it is stopped and restarted during the file cycle (24 hours).



Detector Support Group

Weekly Report, 2018-09-20

- All Gas subsystems have been returned to operational set points.
 - ★ All values are at the previous nominal ranges with the exception of the DC gas quality measurements for the exhaust.
 - ★ The R1-2 O₂ sensor read-back is off scale (> 1000ppm), while the R3 has come down to ~400ppm, previously it was ~70ppm.
 - ★ The moisture content for R1-2 is marginally higher (up to ~450ppm from a pre-storm ~350ppm).
 - ★ The R3 moisture content is ~100ppm, about 50ppm higher than before storm preparations. The progress is being monitored.
- Hall B mechanical has installed an isolation valve for the N₂.
 - ★ This will allow the gas supply to be turned off on one of the areas (space frame or forward carriage) without affecting the other.
 - ★ During installation of the new valve, N₂ was cut off to the RICH for ~25min. DSG has communicated with Hall B Engineering about the need to relay information anytime gas is being shut off, especially to the RICH.

DSG

- Made edits to the Gas Controls document. Added information about the short term SVT set up which used 3 additional MFCs to supply gas to specific areas of the detector in order to provide a flow specification for the manual rotameters.
- Rearranged DC flow diagram so that it reads vertically, top to bottom in order to format properly in the document.