

Pt TS Alarms

Danger: melting solid tgts, burning up motors.

1. Solid target ladder (high) alarm?

1. Reduce solid tgt beam current asap.

2. Phytron (high) alarm?

1. Stop hor. motion. Brake release gets hot.
2. Let it cool before moving again.

3. LH2 pump (high) alarm?

1. Open pump bypass more.
2. Lower pump speed temporarily.

4. Hor. motion table alarm?

1. Change table heater power.

