

Magnets

- Torus magnet power supply SCR faults investigated.
 - ★ SCR wiring was incorrect, therefore SCR was replaced.
- Torus and Solenoid Interlock procedures updated, with the summary of changes performed for the last updated versions.