

Magnets

- Solenoid LV-cRIO controller problems fixed with reboot.
 - * Controller was unable to start program and connect to the network.
 - * Reported cryo alarms on the Solenoid due to wrong temperatures.
- Spreadsheet generated to analyze how the Torus “Out Of Plane Support” forces are affected during the Torus and Solenoid ramp-ups.
- Four network cables connected from cRIO to terminal server