

Torus

- MPS internal faults investigated after Fast dump on the Torus and cross bars circuits were burned.
 - * Found metallic debris inside, most likely from machining work.
 - * Inside of MPS cleaned and debris collected.



Debris found in MPS.



Debris found in MPS; long copper coil is ~6 mm in diameter.