




HDice NMR Software Flowchart




Subroutine 1: Configure setup




Subroutine 2: Check Status of Programs and Instrumentation




Subroutine 3: Test RF Box




Subroutine 4: Check CT-box Calibration Enable



Subroutine 5: Enable Manual Controls



Subroutine 6: Run Mode



Subroutine 7: Reset Instrumentation

