



Quench occurs

Flow rate is unusually high during ramp. Indicating that magnet has higher than normal resistances