
Bias Voltage
50–60 V for 1x1 mm2 SiPM
20–28 V for 3x3 mm2 SiPM
R
C = 10 nF, 100 V
R = 10 KΩ
C
R
C
Amplifier
10x
Signal
SiPM