LSD Deputy Report May 24-May30

Steve Suhring

General Comments:

- Work is going well
 - Some tasks are ahead of schedule
 - Some long range adjustment due to delayed deliveries
- No injuries or close calls
- Good support by Radcon
- Good cooperation with PEPPo and FEL
- 0800 Meetings going well
 - Review Shift reports
 - Review ATLis Work Map
 - Review SAD Calendar
 - Review any Safety items

Specifics:

- PSS decommissioning going per plan
- Warm girders in N & SLinac removed
- C100-5 (2L23) installation on track
- C100-4 (2L22) going into the tunnel today
- RF Separator cavity inspection completed
- Trim rack shuffles begun
- Box supplies disconnected and locked out
- Survey & Alignment distance and level measurements ongoing
- SAB Cooling tower valve replacement completed per plan



2L23 WG Installation

SE Beam Transport Removal



S	A	D	C	al	e	n	d	a	r
Schedul	ed Accel	erator De	own	_				_	

Login

🛶 Week 21 2012 🗰

View ATLis Work Map Help

ſ	Key							
	Good Plan	Tentative Plan	Major Event	Incomplete Task				
	Lock Up	Utility Interruption	Radcon Group	Special Support				
	Subset	New/Changed	🗗 ATLis Task					

~

	Sun	м	т	w	т	F	Sat
21	2012-05-20	21	22	23	24	25	26
Owl	LSD: Michaud	LSD: Michaud	LSD: Michaud	LSD: Michaud	LSD: Suhring PD: Robertson	LSD: Suhring PD: Robertson	LSD: Suhring PD: Robertson PEPPo Run 24/7
Day	PEPPo detector	PEPPo Pb shielding PEPPo solenoid hookup Accel. Control Survey 45 MeV Beam Dump Out C100 3 to EArd/ NLinac FML- Tunnel leak walk S/R TC recom. vent 2116 ins vac pump TS UPS SL C100 Girders out SL21+ vent & remove. PSS Config Cntrl JR12-005 - BOX SUPPLY MOVES N/SAB CHL 2K to 4K to 2K(?) 2L22/23 2K RT bayonet mods DISCONNECT DC POWER DISCONNECT DC POWER PSS dump lock outs	PEPPo S&A Accel. Control IPM2L2X discon. S.E. R bpm S/R TC recom. R100 out at C100-5 to 2L23 IHA&ITV removal PSS Box Duct PSS Config Cntrl 0900 Tunnel	PEPPo S&A PEPPo Pb shielding PEPPo detector source Accel. Control Survey VBV1L22+ thru leak MPS - Bypass 4D00 YR&pipe removal SBPM tear out C100-5 align Pass 5 Sep 4 Kw tst Shunts OFF Shunt Adder sys rmv HMS/Moller cooldn	1500: PEPPo HCO PEPPo detector source chck Accel. Control Survey 1L22+ Girder Removal 1R tear out C100-5 hookup 2S vent & tear out Disconnect magnet cables Decom Trim Racks SAB Cooling Twr Valve Decomm Hall A/B/C PSS 0900 Tunnel training MCC	PEPPo Run 24/7 S&A WA/SL level 1R tear out C100-5 hookup	PEPPo Run 24/7
Swing	1			RF Separator Test		PEPPo Run 24/7	PEPPo Run 24/7
22	2012-05-27	28	29		31	01	02
Owl	LSD: Suhring PD: Robertson PEPPo Run 24/7	LSD: Suhring PD: Robertson PEPPo Run 24/7	LSD: Suhring PD: Robertson PEPPo Run 24/7	LSD: Suhring PD: Robertson PEPPo Run 24/7	LSD: Suhring PD: Bickley PEPPo Run 24/7	LSD: Suhring PD: Bickley PEPPo Run 24/7	LSD: Suhring PD: Bickley PEPPo Run 24/7
Day	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7 C S&A WA/SL level C 100-5 to 2L23 Pass5 cavity rod 2E/2T+ 20 Amp Trim W2/BSY Box PS FEL Run 0900 Tunnel	PEPPo Run 24/7 S&A WA/SL level C100-5 to 2L23 TL alignment 2E/2T+ vent&strip 20 Amp Trim Rack Decom. BSY PSS. XA - g2p disassembly FEL Run DOD Tour	PEPPo Run 24/7 S&A WA/SL level 1R Dipole and Girders C100-5 to 2L23 C100-4 to 2L22 2E/2T+ vent&strip 20 Amp Trim Rack inst FEL Run	PEPPo Run 24/7 Accel. Control Accel. Control 2 1R Dipole and 2 2L23 L-tube and C100-4/2L22 align 2 2E/2T+ 2 20 Amp Trim FEL Run	PEPPo Run 24/7
Swind	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7