

Magnets

- Fast-Daq-Torus-cRIO controller failure debugged.
 - ★ Controller could not run start-up program and connect to the network.
 - ★ Rebooted controller and changed to safe mode.
 - Ethernet connection came back in safe mode, but communication problem persists when switched back to normal mode.