

Magnets

- Replacing eight 100k Ω resistors on quench detector board.