Magnets

• Replaced potentiometers and adjusted to original settings for the Quench Detector board.