Magnets

- Cryo-con units upgraded to latest firmware (version 2.16).
- Communications map of PLC programs for solenoid cooldown generated.

