

Magnets

- Increased priority of PLC time synchronization so they would act as the grandmaster clock.
 - ★ The individual PTP servers for each hall had to be rolled back to a single server located in the CC data center.
 - ★ Priority 1 value of the Solenoid/ Torus PLCs has been changed (128 -> 32) to assign one of them to be the grandmaster clock.