

Torus

- Problems with Cernox temperature sensors in the Low Voltage Chassis #4 solved.
 - ★ Fuse blew in Q0131 card taking out all the Cernox sensors on chassis #4.
 - ★ All Cernox temperature sensors back on-line after card was replaced.