

Torus

- PCB board replaced in Torus Low Voltage chassis # 4.
 - ★ Spare was fixed after changing fuse and removing filter power capacitor.
 - ★ Cernox sensor data from PCB board replacement analyzed.
 - Compared acquired data with and without the capacitor in the PCB board. For all the 12 Cernox sensors found temperature differences.