

# H2 Sensor (sniffer) Alarm

**Danger: System leak, hydrogen fire.**

1. Located above gas panel & target:
  1. Have always been false alarms so far.
  2. Have failed to detect real leaks so far.
2. Clear tgt & gas panel area if personnel in hall.
3. Check system pressure for H2 leaks:
  1. Use archiver to **look** for slow leaks.
    1. Fold in effect of diurnal P variations
  2. If a real leak seems possible, use extreme caution!
    1. H2 flame is odorless & colorless
4. Call experts:
  1. Will sniff with a portable sensor
  2. Will check if sniffer is OK or not.

