



12GeV Machine Safety System  
 Fast Shutdown System  
 Injector Zone  
 Wiring Diagram  
 Based On: Y0001D01  
 Revised: 29 May, 2007