# LSD 2 Week Outlook

Randy Michaud Accelerator Operability




SAD Calendar  Week 20 2012   View ATLis Work Map Help						Good Plan Jentative Plan Major Event Incomplete Task Lock Up Utility Interruption Radoon Group Special Support Subset New/Changed & ATLis Task		
	Sun	М	Т	w	т_	F	Sat	
)	2012-05-13	14	15	16	17	18	19	
Owl						6GeV Ends PD: Michaud	PD: Michaud	
Day			₡ XA PSS LED TS			Open House Prep  © CEBAF ODH cal.  Vent PEPPo  © IPM4D00 out  © Vent 45Mev Dmp  © VBV2L24A thru leak checks  © C100 Rad Survey - tour prep  © NAB Box Supply LTT  © SAB Box Supply LTT  © PSS Config Cntrl JR12-005 - Install  © Tunnel Light PM by FML  LHe lowering	් Tour: Open	
Swing	1				C100 push			
1	2012-05-20	21	22	23	24	25	26	
Owl	PD: Michaud	PD: Michaud	PD: Michaud	PD: Michaud	PD Suhring	PD Suhring	PD Suhring PEPPo Run 24/	
Day	PEPPo detector	PEPPo Pb shielding  PEPPo solenoid hookup  NL S&A  4 45 MeV Beam Dump Out  C700-3 to EArc/ NLinac  FML- Tunnel leak walk  SR TC recom. vent  SL C100 Girders out	PEPPo S&A  NL S&A  © IPM2L2X  © S.E. R bpm  © S/R TC recom.  © R100 out at 2L23	PEPPo S&A PEPPo Pb shielding PEPPo detector NL S&A  ** VBV1L22+ thru  ** S/R TC recom.	1600: PEPPo HCO PEPPo detector NL S&A & 1L22-26 Girder  & S/R TC recom.	PEPPo Run 24/7 ピ S/R TC recom.	PEPPo Run 24/	
		© SL21+ vent & remove. © PSS Config Cntrl JR12-005 - Install © BOX SUPPLY MOVES N/SAB CHL 2K to 4K to 2K(?) © 2L22/23 2K RT bayonet mods	₾ C100-5 to 2L23 ₾ PSS Box Duct 0900 Tunnel training	© C100-5 to 2L23 © HMS/Moller © PSS dump lock	© C100-5 to 2L23  SAB Cooling Two 0900 Tunnel training	e C100-5 to 2L23		
Swing	1					PEPPo Run 24/7	PEPPo Run 24/	
2	2012-05-27	28	29	30	31	01	02	
Owl	PEPPo Run 24/7 PD Suhring	PEPPo Run 24/7 PD Suhring	PEPPo Run 24/7 PD Suhring	PEPPo Run 24/7 PD Suhring	PEPPo Run 24/7 PD Suhring	PEPPo Run 24/7 PD Suhring	PEPPo Run 24/2 PD Suhring	
Day	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7  2º 1R Dipole and 2º C100-5 to 2L23  0900 Tunnel training FEL Run	PEPPo Run 24/7  IR Dipole and C100-5 to 2L23 C100-4 to 2L22  FEL Run	PEPPo Run 24/7  IR Dipole and C100-5 to 2L23 C100-4 to 2L22	PEPPo Run 24/7 ど 1R Dipole and Girders removal ご C100-5 to 2L23 C100-4 to 2L22 ご 2L23: align FEL Run	PEPPo Run 24/2 ☑ C100-5 to	
Swine	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/	
3	2012-06-03	04	05	06	07	08	09	
Owl	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	PEPPo Run 24/7	33	

https://devweb:8181/calendar/view-outlook


## Friday 5/18/12

- Safe out systems
- Open House prep
- PEPPo vacuum & installation
- SLinac valve checks



### Monday - Friday 5/21/12 - 5/25/12

- PEPPo installation, shielding, alignment
  - HCO Thursday ~1500
  - Begin experimental beam delivery Friday ~0800
- Network & target survey & alignment
- SE Recombiner removal
- Cryomodule moves
- CHL to 4K
  - SLinac Transfer Line work



Monday - Friday 5/28/12 - 6/1/12

- PEPPo run 24/7
  - Inj / NLinac beam permit
- Network & target survey & alignment
- SE Recombiner removal
- Cryomodule hookup

