RAM Meeting: Proposal and Discussion

Will Oren, for the LSD Team May 31, 2012



Day-to-Operations

- Biweekly Wednesday 1:30 Resource Meeting
 - Where: MCC until renovations begin then???
 - What:
 - Glance back on previous 2 weeks,
 - Look ahead next 4-6 weeks w/any change orders
 - Safety performance review
 - Project & resource provider presentations where there are "challenges"
 - Who: Work coordinators, Project coordinators, &"Long Shutdown Deputy"



LSD Resource Planning Meeting Agenda

- Glance Back / 2-Week Look Ahead / Change-Control Board (CCB) Report 10 min.
- Safety Report
 5 min.
- Project Management Report 5 min.
- Key Service Provider & Project Lead Reports
 25 min.
- Special Topics (by request)
 5 min.
- Meeting Recap / Parting Shots
 5 min.



Shutdown Work Summary EXAMPLE (Proj. Manager)

Organization: 12 GeV - Accelerator Beam Transport

Name: Mike Bevins

Date: 6/6/12

Last Two Weeks

Work That Went Better Than Expected:

• Teardown of East Spreader - including labeling, disconnects and removal

Work That Went Slower Than Expected, Delays, and Issues:

• NA

Ongoing Shutdown Work

Upcoming Work (3-6 weeks from now) (green = no concerns; yellow = some concerns; red = serious concerns)

Project	Status	On Schedule?	Tasks	Comments/Concerns
ER Tear-out	X	Early	Dipole & girder removal finish &	Going well
			Stand tearout begins	
ER Magnet rework	X	Yes	Refurb & machining	First time for machining – start easy and get more complex. Commission machine tool, transportation is an issue – see below.
Girder rebuild	X	Yes	Rebuild & machine	First time but should be straight forward

New Work Requests Requiring Schedule Changes:

• BPM moves for optics considerations (CASA) were not included in the LSD – needs coordination to fit in at the best time with other work



Shutdown Work Summary EXAMPLE (Proj. Manager)

Significant Problems Pending (delays, technical issues, resource issues, scheduling):
 Crane training not scheduled and will stop work by 1 crew (2 staff for 2 days training) Lack of carts and trucks has slowed work will idle one crew when magnet machining begins The alignment guys are always in the way and they are really picky about what work we do around them. Cry-babies!
Staffing Outlook: New staff working well - down one on head count but managing at this time