Long Shutdown Schedule Development Status

5 April 2012
Dianne Napier
Pat Collins/Heidi Derby

COUNTDOWN TO START OF DOWN:

44 days

Overall Timeline to Baseline

Outstanding Action Items

Overall Timeline to Baseline

- Schedule Validation Process Mid Feb to End of March '12 (need all revisions by April 02...)
- Resource Leveling Process starts April 9th
- Baseline & Start of Change Control Process End of April '12

Schedule Validation Reviews Outstanding Actions

	Hall	A	16	5 F	eb
--	------------------------	---	----	-----	----

- •FML 28 Feb
- Hall B9 March
- •FEL 14 March
- Hall D20 March
- Hall C21 March
- PEPPo & Acc23 March
- 12GeV Acc28 March
- ------ → baseline
- ■12 GeV Hall C 10 April
- ■12 GeV Hall B 29 May

Hall A (Revised Schedule done 9 March)

- Compton design "mini-review" (Ed Folts)
 - Compton can fiducialization
 - Compton alignment task (beamline) adjustments
 - Compton BPM special can (I&C review)

No effect on schedule per email received 27 March.

Complete

FML (Revised Schedule done 7 March)

- Tunnel Dehumidifier replacements locations & durations (possible beamline impacts for some locations).
 (B. Sperlazza)
- Tunnel penetration repair location/WG prototype & duration. (B. Sperlazza)

New schedule received 27 March. These changes are not needed for resource leveling effort to start.

Hall B (Revised Schedule sent 19 March)

- Identify Hot work permit needs (D. Tilles/Pat Collins)
- Add safety system group (SSG) work (D. Tilles/K.
 Mahoney)
- Call out Jan 2013 survey network work in the schedule (line item). (D. Tilles)
- Add electrical techs for the cable removal. (D. Tilles)
- Add RadCon resources (D. Tilles/K. Welch)
- Remove 12GeV items (D. Tilles/W. Akers)

New schedule received, Primavera updated 21 March.

Complete.

FEL (Revised Schedule done 27 March)

Deleted Dark Light, new schedule update received 28 March. Schedule needs to be reviewed.

Hall D (New Schedule sent to Akers 27 March)

- Validate Survey & Alignment estimates/durations throughout the schedule. (T. Carstens/C. Curtis)
- Add fiducializations throughout schedule (T. Carstens/C. Curtis)
- Add alignment of tagger stands (T. Carstens/C. Curtis)
- Add Control network surveys (in Hall & Tagger to Hall D) (T. Carstens/C. Curtis).
- Coordinate power outages. (T. Carstens/B. Merz)
- Break out explicitly non-Hall D labor. (P. Collins/H. Derby)
- Correctly bound the schedule for float calculations. (T. Carstens, T. Whitlatch, P. Collins)
- Remove all cryo labor but not activities. (T. Carstens)
- Remove mech vac tech labor from activities 26, 50, 52, 55 though 58, and 60.
 (T. Carstens)
- Identify FML labor & activity 29 from elec tech to FML. (T. Carstens)
- Coordinate beam dump activities. (T. Carstens, L. Harwood, T. Whitlatch)

New Schedule sent to Akers 27 March & being revised.

Hall C (New Schedule done 22 March)

1. MSINST work?

Original validation items completed.

Accelerator/Peppo (revision in process)

- May 18th maintenance activities are placeholders for now (for the date) will be scheduled by Steve (S. Suhring)
- Folding cryogenic plan in onee it is ready from the cryo group (W. Oren/PMI/S. Suhring)
- Cryomodule removal tasks S&A should not be there for removal tasks. (S. Suhring)
- OLO3 and OLO4 installation breakout S&A activities for a separate line item. (S. Suhring)
- PEPPo May 21 & 22 S&A support needed as a separate line item (S. Suhring)
- Network survey is covered in 12GeV acc for the racetrack so can be removed (S. Suhring)
- Waveguide as founds C. Curtis to discuss with A. Kimber for how to do this, then break out with S&A activities. (this
 is currently summed up with the three weeks of installation). (S. Suhring/C. Curtis)
- Mech tech mech inst tech classifications (S. Suhring/N. Wilson)
- Emptying penetrations (?) what is needed. (S. Suhring/N. Wilson)
- WBS needed for (example): (S. Suhring)
 - Linac maintenance
 - Cryomodule work
- Need to break elec tech into DC/ RF/ I&C etc (S. Suhring/R. Lauze)
- Correct mech vac tech (Heckman) and SRF tech for ion pumps (etc) (S. Suhring)
- Injector segmentation wall (S. Suhring)
 - Need PSS support? (not listed on the activity)
 - This is still being worked as a plan but get the resources right in the meantime
- NL PSS system must be operational for PEPPo running logic associated for other tasks need to be linked (S. Suhring)
- Add EES support for PEPPo running (this is operational support/on-call) but denote so we can capture the labor (S. Suhring)

12GeV Accelerator (Action list 28 March)

- Known Items being worked
 - Stone drops for 1.3.2
 - A few items for 1.3.4 (BT), e.g. LCW lines for arc 10
 - Machine shop hrs for 1.3.4
 - RadCon support
- Surprise: ODH for NL-tagger gas line (I&C/S) Recently identified scope. Scale not yet defined.
- Profile
 - 1.3.3 (Cryo)
 - 1.3.6.4 (Safety)
- Add detail to resource types (ME/MT/MD) in 1.3.5 (Extr)
- Check logic ties of OL/OR 12GeVe work with respect to 0L04/0L03 swap in "Accelerator" Schedule
- Check "Accelerator" schedule for details on 0L04/0L03 swap alignments particularly
- Is ODH monitoring needed for NL to Tagger area?
- Hall A& C energy spectrometer resurvey (open green door).
- NL & SL fix alignment estimates
- PSS Configuration Control (Continuity)
- Final Beam pipe alignment needs to be added
- Penetration Repairs Coordination
- Inter-WBS links once everything is in LSD schedule

