

Magnets

- PLC time-sync configuration changed to use Precision Time Protocol (PTP) timeserver.
- cRIOs updated to LabVIEW 2018 and PTP enabled for time synchronization
- PR submitted for cRIO-9045 for use as spare.