

Detector Support Group

We choose to do these things "not because they are easy, but because they are hard"


Weekly Report, 2020-12-16

Summary

Hall A – SoLID Magnet Controls

Mary Ann Antonioli, Peter Bonneau, Aaron Brown, Pablo Campero, Brian Eng, Tyler Lemon, Marc McMullen

• Developing *Solenoid Menu* HMI screen which provides access to all developed HMI screens



SoLID Solenoid_Menu screen under development

• Completed PLC code to control heat exchanger JT valves

Hall A – GEM Detector Gas Distribution System

Peter Bonneau, Brian Eng, George Jacobs, Mindy Leffel, Tyler Lemon, Marc McMullen

- Developing internal data logger for prototype GEM Gas Flow Readback software
- Updated, using NX12, fabrication drawings for the Gas System Flow Sensor Chassis to remove screen printed channel number labels
 - **★** Channels will be labeled with the names of the detector the channel goes to

Hall B – SVT

Peter Bonneau, Mindy Leffel

 Installed, configured, and tested SVT hardware interlock LabVIEW software package and libraries



Detector Support Group


We choose to do these things "not because they are easy, but because they are hard".

Weekly Report, 2020-12-16

Hall C - NPS

Mary Ann Antonioli, Peter Bonneau, Aaron Brown, Pablo Campero, George Jacobs, Mindy Leffel, Tyler Lemon

- Developing system fault condition flowcharts for the NPS Hardware Interlock System
 - **★** Flowcharts show the reaction of the Hardware Interlock System to a fault condition detected from the environmental sensors within NPS
 - **★** To protect the NPS detector, the Hardware Interlock System will turn off the chillers and/or ramp down the HV depending on the source of the fault
- Developing, using NX12, a three-dimensional model of NPS detector to aid in the design of the Hardware Interlock System



Isometric view of NPS detector and Hall C beamline developed using NX12

- Generated 648 of 1080 PMT Settings screens
- Completed fabrication of all 1100 high voltage divider cables
 - **★** Labeled 100 of 1100 cables
- Generated color coding for Radiall 52-pin connector wiring and posted to DSG website's NPS technical documentation page

SEASON'S GREETINGS AND BEST WISHES FOR A HAPPY NEW YEAR!