


⑤ Lecroy 4616 transform NIM To ECL, then go to VM
 HEL, GMM, LNE from ⑥ and scalars.



Note: ECL cables are already removed when I make the record of the cable map now.