



# Jefferson Lab Alignment Group Data Transmittal

TO: K. Welch, J. Willoughby

DATE: 03 Jun 2015

FROM: J. Dahlberg

Checked:

# : M1647

**DETAILS:**

Data: CivilSurvey\NECRManhole\150602a

Below are the results from the C-18 manhole communication box survey. Note that because the communication box was under several feet of water, the manhole cover was measured to define the horizontal offsets, and the top of the box was measured for the vertical offsets. The inside tunnel wall was measured downstairs at the same distance along beam to define its location. Values are in feet.

