

EIC Beamline R & D Status

Detector Support Group December 7, 2022



December 7, 2022

EIC Test Stand

Pablo Campero, Brian Eng, George Jacobs, Marc McMullen

- · Tested compressed air line and determined there was too much pressure for the relief valve
 - * The DA added a regulator; the line is approved for use
 - · Mounted pipe stands to the table and glued RTD wires to pipe ends



· Tested the RTDs using LabVIEW



5